

Attachment 2

**UP-DATED
PHOTOGRAPH
DESCRIPTIONS
2-15-08**

**THE FOLLOWING
PHOTOS SHOW:**

1. Meco building #4.



2. Overview of roof.



3. Damaged from flying debris.



4. Loose screws.



5. Seams and screws sealed.



6. Punctured by flying debris.



7. Hole from flying debris.



8. Buckled from flying debris.



9. Missing rake trim also vent is damaged.



10. Missing insulation.



11. Overview of canopy.



LAST PAGE