

Attachment 2

**UP-DATED
PHOTOGRAPH
DESCRIPTIONS
2-15-08**

**THE FOLLOWING
PHOTOS SHOW:**

1. Meco building #5.



2. Overview of roof.



3. Damaged.



4. Missing panels over existing roof.




5. Lifted and missing panels over existing roof.



6. Detached eave trim.



7. Buckled and torn.



8. Impact from flying debris.




9. Damaged by flying debris.



10. Damaged by flying debris.



11. Hole from flying debris.



12. Roof panel and insulation damaged from flying debris.



13. Detached insulation.



14. Damaged eave



15. Missing eave and rake trim also down spout.



16. Damaged gutter and missing down spout.



17. Detached.



LAST PAGE