



Roof framing members that have been painted.



Roof framing members that have been painted.




Roof framing member that has been painted.



Roof framing member that has been painted.




Apparent location of previous fire.



Crack in brick veneer.

Crack in brick veneer.

Weep holes covered by landscaping.



Crack in brick veneer.



Crack in brick veneer.