



DAMAGED ROOF END RAKE
N.T.S.




DAMAGED ROOF AND VENTILATORS
N.T.S.



DAMAGED FIBERGLASS ROOF PANELS
N.T.S.



MISSING GUTTER
N.T.S.



DAMAGED OVERLAPPING PANELS
N.T.S.



DAMAGED ROOF AND VENTILATORS
N.T.S.



OVERVIEW OF ROOF
N.T.S.



DAMAGED FIBERGLASS ROOF PANELS
N.T.S.




DAMAGED OVERLAPPING PANELS
N.T.S.



DAMAGED VENTILATOR BASE
N.T.S.



DAMAGED ROOF RIDGE
N.T.S.



CORRODED GUTTERS
N.T.S.



ROOF NEAR UTILITY POLE
N.T.S.




DAMAGED VENTILATOR
N.T.S.



DAMAGED ROOF PANELS
N.T.S.



DAMAGED ROOF PANELS
N.T.S.



DAMMON
ENGINEERING, INC.

CHIEF ENGINEER
EMMETT
DAMMON, P.E.
CHIEF ARCHITECT
ROBERT
WILTSE

1095 FLORIDA AVENUE
SUDBELL, LA. 70456
OFFICE: 985-649-5832
FAX: 985-641-5950

WEBSITE:
WWW.DAMMONENGINEERING.COM
EMAIL:
DAMMONENG@Bellsouth.net

ARCHITECTURE
ENGINEERING
STUDIES
PLANNING

INVESTIGATION
EXPERT WITNESS

**BUILDING ROOF
RECOATING**

PEARL RIVER
HIGH SCHOOL
INDUSTRIAL ARTS
BUILDING
PEARL RIVER, LA

EXISTING
ROOF PICTURES

REV:

SCALE: AS NOTED

JOB#: 2043

DATE: 1-19-10

SHEET

A-2

OF