

**Attachment 2**

---

**UP-DATED  
PHOTOGRAPH  
DESCRIPTIONS  
2-15-08**

---

**THE FOLLOWING  
PHOTOS SHOW:**

1. Meco building #1.



2. Roof overview.



3. Damaged edge.



- 4. Missing gutter and eve trim.



- 5. Damaged canopy collapsing.



- 6. Detached eave trim.



7. Lifted panel fasteners pulled out.



**LAST PAGE**