

**Attachment 2**

---

**UP-DATED  
PHOTOGRAPH  
DESCRIPTIONS  
2-15-08**

---

**THE FOLLOWING  
PHOTOS SHOW:**

1. Meco building 2.



2. Lifted also damaged vent.




3. Buckled.



- 4. Buckled and torn by flying debris.



- 5. Hole from flying debris.



- 6. Buckled.



7. Dented and torn from flying debris.



8. Lifted.



9. Buckled and missing rake trim.



10. Vent pipe broken off flush with roof.



11. Lifted.



13. Rake trim missing.



14. Lifted and buckled.




15. Missing and detached vents also damaged side panels.



16. Lifted.



17. Damaged gutter.



18. Damaged down spout.



19. Buckled and torn.



**LAST PAGE**