

Attachment 2

**UP-DATED
PHOTOGRAPH
DESCRIPTIONS
2-15-08**

**THE FOLLOWING
PHOTOS SHOW:**


1. Meco Building 3



2. Overview damaged roof.



3. Damaged vent.



4. Overview of loose downspout lying on roof.



LAST PAGE