



1) GIRDERS 2) BEAMS 3) COLUMNS

- Material:** Steel Wood Concrete block Brick
- Condition:** Satisfactory **Marginal** (2) Poor
- Sagging (beams – see Photo 21:1)
- Moisture stains (see Photo 21:2)



Photo 21:1



Photo 21:2

This issue is consistent at the same locations on all of the support beams.

JOISTS

- Material:** Steel Wood
- 2x6 2x8 2x10 2x12
- Condition:** **Satisfactory** Marginal Poor

SUBFLOOR

- Material:** Not visible
- Condition:** Unknown

INSULATION

- Present:** Yes No