

THIRD EDITION

FEMA 55/May 2000

Coastal Construction Manual

**Principles and Practices of
Planning, Siting, Designing,
Constructing, and Maintaining
Residential Buildings
in Coastal Areas**



Federal Emergency Management Agency

Mitigation Directorate

500 C Street, SW.

Washington, DC 20472

Volume I:

Introduction

Historical Perspective

Coastal Environment

Fundamentals

Identifying and Evaluating
Site Alternatives

Investigating Regulatory
Requirements

Identifying Hazards

Siting

Financial and Insurance
Implications



IMPORTANT

TO RECEIVE PERIODIC UPDATES TO THE FEMA *Coastal Construction Manual*, please fill out the coupon provided below, fold along the dotted lines, add postage, and return to the address shown below.

COMMENTS CONCERNING THE FEMA *Coastal Construction Manual* can be submitted to FEMA by e-mail at building.science@fema.gov.

Please add my name to FEMA mailing list FE-55 and send me updates to the FEMA *Coastal Construction Manual* as they are issued.

Name (Please Print)

Address

City

State

Zip

Updates will be provided to the user listed above as they are produced.

**Place
Postage
Here**

Federal Emergency Management Agency

P. O. Box 2012
Jessup, MD 20794-2012

Dedication



Ray Fox (1923-1997)

FEMA is honored to dedicate this edition of the *Coastal Construction Manual* to the memory of Ray Fox.

Ray Fox, Chairman of the Civil Engineering Department at George Washington University in Washington, DC, was a national expert on coastal construction. A consultant to FEMA on many projects, Ray was the principal writer of the first two editions of the *Coastal Construction Manual*. Ray was dedicated to improving the quality of buildings constructed in coastal areas. He emphasized that a building was only as strong as its weakest link. “Connections, connections, connections!” was the phrase he often used to stress the importance of adequately connecting all components of a well-designed building. There was no compromise by Ray when it came to building design. He would often say “If you can’t build it right then don’t build it.”

Foreword

This is the third edition of the Federal Emergency Management Agency’s *Coastal Construction Manual*. The manual provides technical guidance for evaluating natural hazards in coastal areas and mitigating those hazards through sound siting, design, construction, and maintenance practices. It is not the intent of this manual to encourage the construction of buildings in hazardous coastal areas. Rather, when such construction does occur, following the recommendations in this manual will help ensure that the buildings are sited, designed, constructed, and maintained in a manner that reduces their vulnerability to natural hazards and therefore reduces the potential for damage.

This manual is not a design document. It does, however, provide detailed guidance and a “best practices” approach to the construction of coastal residential buildings. The user must assume responsibility for adapting and/or supplementing the information contained herein to meet the particular requirements of a project. This manual is intended to complement and supplement the **National Flood Insurance Program** regulations and the codes, ordinances, laws, and regulations of state and local governments.

As a guidance document tailored to the needs of both public and private sector users—including design professionals, contractors, and community building officials—this manual contributes to the goal of reducing the loss of life, damage, and costs that result from natural disasters. An important part of FEMA’s mission is helping communities take action to protect themselves from the devastating effects of natural disasters. FEMA has used a variety of mechanisms to transfer information to communities and individuals about the latest hazard mitigation practices. This manual adds to that effort by providing technical information on the best practices for reducing damage in coastal areas. Historically, the most successful application of hazard mitigation practices has rested on cooperation between the private sector and local government. The information in this manual will facilitate the cooperation that is so vital in meeting hazard mitigation goals.

Table of Contents

Volume I

	Page
Dedication	i
Foreword	iii
Acknowledgments	xlv
Acronyms and Abbreviations	xlix
Metrification	liii
Chapter 1	
Introduction	1-1
1.1 Background	1-1
1.2 Purpose	1-1
1.3 Organization	1-3
1.4 Using the Manual	1-6
Chapter 2	
Historical Perspective	2-1
2.1 Introduction	2-1
2.2 Coastal Flood and Wind Events	2-1
2.2.1 Northeast Atlantic Coast	2-1
2.2.2 Southeast Atlantic Coast and Caribbean	2-8
2.2.3 Gulf of Mexico Coast	2-21
2.2.4 Pacific Coast	2-27
2.2.5 Hawaii and U.S. Pacific Territories	2-30
2.2.6 Great Lakes	2-33
2.3 Lessons Learned	2-35
2.3.1 Hazard Identification	2-35
2.3.2 Siting	2-37
2.3.3 Design	2-38

2.3.4 Construction 2-40

2.3.5 Maintenance 2-41

2.4 References 2-41

Chapter 3

Coastal Environment 3-1

3.1 Introduction 3-1

3.2 United States Coastline Characteristics 3-4

3.2.1 Atlantic Coast 3-5

3.2.2 Gulf of Mexico Coast 3-6

3.2.3 Pacific Coast 3-6

3.2.4 Great Lakes Coast 3-7

3.2.5 Coast of Alaska 3-7

3.2.6 Coast of Hawaii and Pacific Territories 3-7

3.2.7 Coast of Puerto Rico and the U.S. Virgin Islands 3-7

3.3 Coastal Flood Hazards 3-8

3.3.1 Wave Heights and Wave Crest Elevations 3-10

3.3.2 Wave Runup 3-10

3.3.3 Erosion Considerations and Flood Hazard Mapping 3-11

3.4 References 3-13

Chapter 4

Fundamentals 4-1

4.1 Introduction 4-1

4.2 Hazards, Risk Assessment, and Risk Management 4-4

4.2.1 Risk Assessment 4-5

4.2.2 Risk Management 4-8

4.3 Cost Considerations 4-12

4.4 References 4-14

Chapter 5

Identifying and Evaluating Site Alternatives 5-1

5.1 Introduction 5-1

5.2 Identifying Suitable Property for Coastal Residential Structures 5-4

5.3	Compiling Information on Coastal Property	5-6
5.3.1	Sources of Information	5-10
5.3.2	Property Disclosure Requirements	5-12
5.4	Evaluating Hazards and Potential Vulnerability	5-15
5.4.1	Define Coastal Hazards Affecting the Property	5-15
5.4.2	Evaluate Hazard Effects on the Property	5-16
5.5	Decision Time	5-17
5.6	References	5-18

Chapter 6

	Investigating Regulatory Requirements	6-1
6.1	Introduction	6-1
6.2	Land Use Regulations	6-1
6.3	Building Codes and Standards	6-3
6.4	National Flood Insurance Program	6-5
6.4.1	Background	6-5
6.4.2	Determination of BFEs and Flood Insurance Zones in Coastal Flood Hazard Areas	6-7
6.4.3	Minimum Regulatory Requirements Imposed by Communities Participating in the NFIP	6-8
6.5	Recommendations for Exceeding Minimum NFIP Regulatory Requirements	6-15
6.5.1	Non-Coastal A Zones	6-15
6.5.2	Coastal A Zones and V Zones	6-16
6.5.3	Summary	6-17
6.6	Coastal Barrier Resources Act of 1982	6-22
6.7	Coastal Zone Management Regulations	6-22
6.8	References	6-24

Chapter 7

	Identifying Hazards	7-1
7.1	Introduction	7-1
7.2	Natural Hazards Affecting Coastal Areas	7-1
7.2.1	Tropical Cyclones and Coastal Storms	7-2

	7.2.2	Tsunamis	7-9
7.3		Coastal Flooding	7-13
	7.3.1	Hydrostatic Forces	7-13
	7.3.2	Hydrodynamic Forces	7-14
	7.3.3	Waves	7-16
	7.3.4	Floodborne Debris	7-18
	7.3.5	Sea-Level Rise and Lake-Level Rise	7-21
7.4		High Winds	7-23
	7.4.1	Speedup of Winds Due to Topographic Effects	7-27
	7.4.2	Windborne Debris and Rainfall Penetration	7-27
	7.4.3	Tornadoes	7-27
7.5		Erosion	7-28
	7.5.1	Describing and Measuring Erosion	7-36
	7.5.2	Causes of Erosion	7-39
7.6		Earthquakes	7-54
7.7		Other Hazards and Environmental Effects	7-61
	7.7.1	Subsidence and Uplift	7-61
	7.7.2	Landslides and Ground Failures	7-61
	7.7.3	Salt Spray and Moisture	7-63
	7.7.4	Rain	7-66
	7.7.5	Hail	7-67
	7.7.6	Wood Decay and Termites	7-67
	7.7.7	Wildfire	7-67
	7.7.8	Floating Ice	7-68
	7.7.9	Snow	7-68
	7.7.10	Atmospheric Ice	7-68
7.8		Coastal Hazard Zones	7-68
	7.8.1	NFIP Hazard Zones	7-70
	7.8.2	Examples of State and Community Coastal Hazard Zone Delineation	7-78

7.8.3 Other Risk Assessment Approaches 7-78

7.9 Translating Hazard Information into Practice 7-78

7.9.1 Is an Updated or a More Detailed Flood Hazard Assessment Needed? 7-79

7.9.2 Updated or Revised Flood Hazard Assessments 7-81

7.10 References 7-84

Chapter 8

Siting 8-1

8.1 Introduction 8-1

8.2 Siting Considerations 8-1

8.3 Raw Land Development: Infrastructure and Lot Layout 8-4

8.3.1 Introduction 8-4

8.3.2 Practices To Avoid and Recommended Alternatives 8-7

8.4 Infill Development: Siting a Building on an Existing Lot 8-15

8.4.1 Introduction 8-15

8.4.2 Practices To Avoid and Recommended Alternatives 8-17

8.5 Influence of Beach Nourishment and Dune Restoration on Siting Decisions 8-20

8.6 References 8-22

Chapter 9

Financial and Insurance Implications 9-1

9.1 Introduction 9-1

9.2 Benefit and Cost Implications of Siting, Design, and Construction 9-2

9.3 Hazard Insurance 9-10

9.3.1 Flood Insurance 9-11

9.3.2 Wind Insurance 9-18

9.3.3 Earthquake Insurance 9-20

9.4 References 9-21

Volume II

Chapter 10	Introduction to Volume II	10-1
10.1	Purpose and Organization	10-1
10.2	Important Reminders	10-4
Chapter 11	Determining Site-Specific Loads	11-1
11.1	Introduction	11-1
11.2	Dead Loads	11-3
11.3	Live Loads	11-3
11.4	Concept of Tributary or Effective Area and Application of Loads to a Building	11-4
11.5	Snow Loads	11-4
11.6	Flood Loads	11-6
11.6.1	Design Flood	11-6
11.6.2	Design Flood Elevation (DFE)	11-6
11.6.3	Design Flood Depth (d_s)	11-7
11.6.4	Wave Setup (d_{ws}) Contribution to Flood Depth	11-9
11.6.5	Design Wave Height (H_b)	11-9
11.6.6	Design Flood Velocity (V)	11-9
11.6.7	Hydrostatic Loads	11-11
11.6.8	Wave Loads	11-14
11.6.9	Hydrodynamic Loads	11-18
11.6.10	Debris Impact Loads	11-22
11.6.11	Localized Scour	11-26
11.6.12	Flood Load Combinations	11-29
11.7	Tsunami Loads	11-36
11.8	Wind Loads	11-36
11.8.1	Main Wind Force Resisting System	11-39
11.8.2	Components and Cladding	11-42
11.9	Tornado Loads	11-48

11.10	Seismic Loads	11-48
11.11	Load Combinations	11-57
11.12	References	11-61

Chapter 12

	Designing the Building	12-1
12.1	The Design Process	12-1
12.2	Step 1 – Determining Loads	12-2
12.3	Step 2 – Applying Loads to the Building	12-3
	12.3.1 Failure Modes	12-4
	12.3.2 Load Path	12-14
	12.3.3 Structural Building Systems	12-16
	12.3.4 Construction Materials	12-22
	12.3.5 Building Layouts and Architectural Shapes	12-23
12.4	Step 3 – Determine Forces at Connections and Stresses in Materials	12-25
	12.4.1 Getting Started	12-25
	12.4.2 Analyze Load Path Links	12-32
	12.4.3 Foundation Design	12-59
	12.4.4 Other Important Load Paths	12-75
	12.4.5 Bracing	12-76
	12.4.6 Breakaway Wall Enclosures	12-85
12.5	Step 4 – Develop Connections at Each Link	12-86
	12.5.1 Connection Choices	12-86
	12.5.2 Link #1 – Roof Sheathing to Roof Framing	12-88
	12.5.3 Link #2 – Roof Framing to Exterior Walls	12-88
	12.5.4 Link #3 – Top Wall Plate to Wall Studs	12-90
	12.5.5 Link #4 – Wall Sheathing to Window Header	12-91
	12.5.6 Link #5 – Window Header to Exterior Wall	12-91
	12.5.7 Link #6 – Wall to Floor Framing	12-91
	12.5.8 Link #7 – Floor Framing to Support Beam	12-92

12.5.9 Link #8 – Floor Support Beam to Pile Foundation 12-92

12.6 Step 5 – Select Building Materials 12-93

12.6.1 Introduction 12-93

12.6.2 Selection of Materials for Foundations
and Enclosures Below the DFE 12-95

12.6.3 Selection of Materials for Use Above the DFE 12-97

12.6.4 Material Combinations 12-97

12.6.5 Fire Safety Considerations 12-99

12.6.6 Corrosion 12-101

12.6.7 Additional Environmental Considerations 12-101

12.7 Design of the Building Envelope 12-103

12.7.1 Floors for Elevated Buildings 12-104

12.7.2 Exterior Walls and Soffits 12-105

12.7.3 Doors and Door Assemblies 12-108

12.7.4 Windows, Shutters, and Skylights 12-112

12.7.5 Roof Coverings 12-120

12.7.6 Roof Ridge Vents 12-140

12.8 Utilities/Mechanical Equipment 12-142

12.8.1 Elevators 12-142

12.8.2 Design of Exterior-Mounted Mechanical Equipment 12-143

12.8.3 Design of Interior Mechanical Equipment 12-146

12.8.4 Electrical, Telephone, and Cable TV Systems 12-147

12.8.5 Water and Wastewater Systems 12-151

12.9 Appurtenant Structures 12-153

12.9.1 Decks, Gazebos, and Covered Porches Attached
to Buildings 12-153

12.9.2 Walkways, Sidewalks, and Other Ground-Level
Structures 12-154

12.9.3 Access to Elevated Buildings 12-157

12.9.4 Pools and Hot Tubs 12-157

12.9.5 Boat Houses 12-158

	12.9.6 Storage Buildings	12-159
12.10	References	12-160
Chapter 13	Constructing the Building	13-1
13.1	Introduction	13-1
13.2	Foundation Construction	13-2
	13.2.1 Layout	13-2
	13.2.2 Soils	13-6
	13.2.3 Pile Foundation	13-9
	13.2.4 Masonry Foundation Construction	13-15
	13.2.5 Concrete Foundation Construction	13-17
	13.2.6 Wood Foundation Construction	13-19
	13.2.7 Foundation Material Durability	13-20
	13.2.8 Field Preservative Treatment	13-25
	13.2.9 Substitutions	13-26
	13.2.10 The Top Foundation Issues for Builders	13-26
	13.2.11 Inspection Points	13-27
13.3	Structural Frame	13-27
	13.3.1 Floor Framing	13-31
	13.3.2 Wall Framing	13-34
	13.3.3 Roof Framing	13-38
	13.3.4 The Top Structural Frame Issues for Builders	13-40
13.4	Building Envelope	13-41
	13.4.1 Substitution of Building Envelope Materials	13-42
	13.4.2 Building Envelope Inspection Points	13-42
	13.4.3 The Top Building Envelope Issues for Builders	13-43
13.5	Appurtenant Structures	13-44
	13.5.1 Decks	13-44
	13.5.2 Storage Buildings	13-46
	13.5.3 Swimming Pools and Hot Tubs	13-46

13.5.4 Walkways and Sidewalks 13-48

13.6 Utility/Mechanical Equipment 13-49

13.6.1 Elevators 13-49

13.6.2 Heating, Ventilating, and Cooling (HVAC) Systems 13-50

13.6.3 Electrical Systems 13-53

13.6.4 Water and Wastewater Systems 13-53

13.6.5 Tanks 13-54

13.7 References 13-55

Chapter 14

Maintaining the Building 14-1

14.1 Introduction 14-1

14.2 Effects of Coastal Environment 14-3

14.2.1 Corrosion 14-3

14.2.2 Termites 14-3

14.2.3 Moisture 14-3

14.2.4 Weathering 14-5

14.3 Building Elements That Require Frequent Maintenance 14-5

14.3.1 Siding 14-5

14.3.2 Roofs 14-6

14.3.3 Glazing 14-7

14.3.4 Outdoor Mechanical/Electrical Equipment 14-8

14.3.5 Decks/Exterior Wood 14-8

14.3.6 Metal Connectors 14-9

14.4 Maintenance Techniques Required for Natural Hazards 14-10

14.4.1 Flooding 14-10

14.4.2 Seismic and Wind 14-10

14.5 Retrofit Opportunities 14-11

14.6 Retrofit Costs 14-15

14.7 References 14-16

Volume III

Appendixes

A	Individuals Contacted
B	Glossary
C	FEMA Offices
D	NFIP State Coordinating Agencies
E	State Coastal Zone Management Agencies
F	Information Sources
G	Examples of State and Community Coastal Erosion Studies and Hazard Zone Maps
H	FEMA NFIP Technical Bulletins
I	Dune Walkover Guidance
J	Material Durability in Coastal Environments
K	Galvanized Roofing Attachment
L	Swimming Pool Design Guidance

List of Figures

Chapter 1

Introduction

Figure 1-1	General process flowchart for coastal construction.	1-4
Figure 1-2	Example of chapter summary table.	1-8

Chapter 2

Historical Perspective

Figure 2-1	1938 Hurricane. Schell Beach, Guilford, Connecticut, before and after the storm.	2-2
Figure 2-2	1962 Mid-Atlantic storm. Extreme damage to homes along the beach at Point-o-Woods, Fire Island, New York.	2-3
Figure 2-3	Hurricane Bob (1991) destroyed 29 homes along this reach of Mattapoisett, Massachusetts.	2-5
Figure 2-4	October 1991 northeaster damage to homes at Scituate, Massachusetts.	2-7
Figure 2-5	1992 storm impacts at Dewey Beach, Delaware.	2-7
Figure 2-6	Building damage from 1926 hurricane, Miami, Florida.	2-9
Figure 2-7	March 1989 northeaster. This plain concrete perimeter grade beam cracked in several places.	2-11
Figure 2-8	March 1989 northeaster. Although this house seems to have lost only several decks and a porch, the loss of supporting soil leaves its structural integrity in question.	2-11
Figure 2-9	March 1989 northeaster. Failure of cross-bracing.	2-12
Figure 2-10	March 1989 northeaster. Deck pile broken by debris impact.	2-12
Figure 2-11	Hurricane Hugo (1989), Garden City Beach, South Carolina. House on pilings survived while others did not.	2-13
Figure 2-12	Hurricane Hugo (1989), South Carolina. Failure of reinforced masonry column.	2-14

Figure 2-13	Hurricane Andrew (1992). Roof structure failure due to inadequate bracing.	2-15
Figure 2-14	Hurricane Marilyn (1995). This house lost most of its metal roof covering.	2-16
Figure 2-15	Hurricane Marilyn (1995). The roof of this house was penetrated by a large wind-driven missile (metal roof covering).	2-17
Figure 2-16	Hurricane Fran (1996). Many oceanfront houses built before the enactment of the 1986 North Carolina State Code were found to be leaning or destroyed.	2-18
Figure 2-17	Hurricane Georges (1998). Coastal building in Puerto Rico damaged by storm surge and waves.	2-20
Figure 2-18	Galveston on two levels—the area at the right has already been raised; on the left, houses have been lifted, but the land is still low.	2-21
Figure 2-19	Hurricane Frederic (1979). Effects of wind and water forces on unbraced pile foundation.	2-23
Figure 2-20	Hurricane Opal (1995), Bay County, Florida. Building damage from erosion and undermining.	2-25
Figure 2-21	Hurricane Georges (1998), Dauphin Island, Alabama. As a result of erosion, scour, and inadequate pile embedment, the house on the right was washed off its foundation and into the house on the left.	2-27
Figure 2-22	1964 Good Friday earthquake. Damage in Kodiak City, Alaska, caused by the tsunami of the 1964 Alaskan earthquake.	2-28
Figure 2-23	Winter coastal storms, California and Oregon (1997–1998). House in Pacifica, California, undermined by bluff erosion.	2-30
Figure 2-24	Hurricane Iniki (1992). Non-elevated house at Poipu Beach that floated off its foundation and was pinned against another house and destroyed by waves.	2-31
Figure 2-25	Hurricane Iniki (1992). Undermining of shallow footings supporting columns at Poipu Beach due to lack of sufficient embedment below erosion level.	2-31

Figure 2-26 Typhoon Paka (1997). Although damaged by the storm, the concrete house in the upper part of the photograph survived, while the wood-frame house next to it was destroyed. 2-32

Figure 2-27 House on southeastern shoreline of Lake Michigan undermined by erosion during storm of November 1951. 2-33

Figure 2-28 August 1988. Erosion along the Lake Michigan shoreline at Holland, Michigan, resulting from high lake levels and storm activity. 2-35

Chapter 3

Coastal Environment

Figure 3-1 Coastal region terminology. 3-1

Figure 3-2 Principal components of a typical sediment budget for a barrier island and barrier spit shoreline. 3-3

Figure 3-3 Principal components of a typical sediment budget for a mainland shoreline backed by bluffs and dunes. 3-3

Figure 3-4 Generalized depiction of erosion process along a rocky coastline. 3-4

Figure 3-5 The United States coastline. 3-5

Figure 3-6 This portion of a FIRM shows a coastal Special Flood Hazard Area (SFHA) (dark gray), the 500-year flood hazard area (light gray), coastal Base Flood Elevations (BFEs) (numbers in parentheses), and flood insurance rate zones (AE and VE = SFHA, VE = Coastal High Hazard Area, X = areas outside the SFHA). 3-9

Figure 3-7 Typical shoreline-perpendicular transect used in the analysis of stillwater and wave crest elevations. 3-9

Figure 3-8 Determination of BFE in coastal flood hazard areas where wave crest elevations exceed wave runup elevations (Zones A and V). 3-11

Figure 3-9 Where wave runup elevations exceed wave crest elevations, the BFE is equal to the runup elevation. 3-11

Figure 3-10	Portions of pre- and post-Hurricane Fran FIRMs for Surf City, North Carolina.	3-12
-------------	--	------

Chapter 4

Fundamentals

Figure 4-1	Although this North Carolina house appears to be a structural success, long-term erosion has left it standing on the beach.	4-2
Figure 4-2	These three South Carolina houses were built at least 100 feet landward of the vegetation line, but rapid erosion associated with a nearby tidal inlet has left the houses standing on the beach.	4-2
Figure 4-3	These Oregon townhouses were built as little as 10 feet landward of a 170-foot-high bluff, after an expert assured the local government that the site was suitable.	4-3
Figure 4-4	Hurricane Fran (1996). This North Carolina house was set back from the shoreline, and safe from long-term and storm-induced erosion. However, high winds from the storm caused heavy damage to the porch walls and roof.	4-3

Chapter 5

Identifying and Evaluating Site Alternatives

Figure 5-1	Evaluation of coastal property.	5-2
Figure 5-2	Coastal development sometimes involves development of subdivisions or large residential projects from raw land.	5-3
Figure 5-3	Narrowing the search for coastal property suitable for development or redevelopment requires careful consideration of a variety of property and area characteristics, including the nature and success of previous erosion control efforts (e.g., groins and revetments at this Massachusetts community).	5-5
Figure 5-4	Development near tidal inlets requires special attention, as evidenced by earlier shorelines superimposed on this 1974 photograph.	5-9

Figure 5-5 Siting and design should include consideration of multiple storms or hazards within a short period, whose cumulative effects can exceed those of a design-level event. 5-17

Chapter 6

Investigating Regulatory Requirements

Figure 6-1 States that have a mandatory building code based on one of the model building codes. 6-4

Figure 6-2 Minimum NFIP A-zone requirements. 6-11

Figure 6-3 Minimum NFIP V-zone requirements. 6-13

Figure 6-4 Recommended elevation for buildings in coastal A zones and V zones. 6-16

Chapter 7

Identifying Hazards

Figure 7-1 Hurricane Frederic (1979). Storm surge and waves overtopping a coastal barrier island in Alabama. 7-2

Figure 7-2 Classification (by Saffir-Simpson scale) of landfalling tropical cyclones along the U.S. Atlantic and Gulf of Mexico coasts, 1900–1996. 7-4

Figure 7-3 Total number of direct and indirect impacts by landfalling hurricanes for coastal counties from Texas to Maine, 1900–1994. 7-5

Figure 7-4 Classification (by Dolan-Davis scale) of northeasters at Cape Hatteras, North Carolina, 1942–1984. 7-8

Figure 7-5 March 1962 northeaster. Flooding, erosion, and overwash at Fenwick Island, Delaware. 7-8

Figure 7-6 Hilo, Hawaii. Damage from the 1960 Tsunami. 7-10

Figure 7-7 Tsunami elevations with a 90-percent probability of not being exceeded in 50 years – western United States, Alaska, and Hawaii. 7-12

Figure 7-8 Hurricane Hugo (1989), Garden City, South Carolina. Intact houses were floated off their foundations and carried inland. 7-13

Figure 7-9	Storm surge and wave runup across boardwalk at South Mission Beach, California, during January 1988 storm.	7-14
Figure 7-10	Hurricane Opal (1955). Flow channeled between large engineered buildings (circled) at Navarre Beach, Florida, scoured a deep channel across the island and damaged infrastructure and houses.	7-15
Figure 7-11	Pile-supported house in the area of channeled flow shown in Figure 7-10.	7-15
Figure 7-12	This house was also in an area of channeled flow during Hurricane Opal. The house was undermined and washed into the bay behind the barrier island; as a result, the house is now a total loss and a threat to navigation.	7-16
Figure 7-13	Storm waves breaking against a seawall in front of a coastal residence at Stinson Beach, California.	7-16
Figure 7-14	Wave runup beneath elevated buildings at Scituate, Massachusetts, during the December 1992 northeast storm.	7-17
Figure 7-15	Damage to oceanfront condominium in Ocean City, New Jersey, caused by wave runup on a timber bulkhead.	7-17
Figure 7-16	Hurricane Fran (1996). Concrete slab-on-grade flipped up by wave action came to rest against two foundation members, generating large, unanticipated loads on the foundation.	7-18
Figure 7-17	Hurricane Georges (1998). A pile-supported house at Dauphin Island, Alabama, was toppled and washed into another house, which suffered extensive damage.	7-19
Figure 7-18	Hurricane Opal (1995). Pier pilings were carried over 2 miles by storm surge and waves before they came to rest against this elevated house in Pensacola Beach, Florida.	7-20
Figure 7-19	Hurricane Fran (1996). Debris lodged beneath a Topsail Island, North Carolina, house elevated on unreinforced masonry walls.	7-20

Figure 7-20 March 1975 storm. Drift logs driven into coastal houses in Sandy Point, Washington. 7-21

Figure 7-21 Estimates of relative sea level rise along the continental United States in millimeters per year. 7-22

Figure 7-22 Monthly bulletin of lake levels for Lakes Michigan and Huron. 7-22

Figure 7-23 ASCE 7-98 wind speed map. 7-24

Figure 7-24 Hurricane Andrew (1992). End wall failure of typical masonry first floor/wood-frame second floor building in Dade County, Florida. 7-26

Figure 7-25 Hurricane Iniki (1992), Kauai County, Hawaii. Loss of roof sheathing due to improper nailing design and schedule. 7-26

Figure 7-26 Dune erosion in Walton County, Florida, caused by Hurricane Eloise (1975). 7-29

Figure 7-27 Erosion and revetment damage in St. Johns County, Florida, caused by the November 1984 northeast storm. 7-29

Figure 7-28 Hurricane Opal (1995). Failure of seawall in Bay County, Florida, led to undermining and collapse of the building behind the wall. 7-30

Figure 7-29 Long-term erosion at South Bethany Beach, Delaware, has lowered ground elevations beneath buildings and left them more vulnerable to storm damage. 7-30

Figure 7-30 Erosion undermining a coastal residence at Cape Shoalwater, Washington. 7-31

Figure 7-31 Removal of Hurricane Opal overwash from road at Pensacola Beach, Florida. 7-31

Figure 7-32 Hurricane Bonnie (1998). Overwash on Topsail Island, North Carolina. 7-32

Figure 7-33 Hurricane Fran (1996). Beach and building damage at North Topsail Beach, North Carolina. 7-32

Figure 7-34 A breach was cut across Nauset Spit on Cape Cod, Massachusetts, by a January 1987 northeaster. 7-33

Figure 7-35 1988 photograph of undermined house at Chatham, Massachusetts. 7-33

Figure 7-36	Cape San Blas, Gulf County, Florida, in November 1984, before Hurricane Elena.....	7-34
Figure 7-37	Cape San Blas, Gulf County, Florida, in November 1985, after Hurricane Elena.	7-34
Figure 7-38	Long-term erosion along the Lake Michigan shoreline in Ozaukee County, Wisconsin, increases the threat to residential buildings outside the floodplain.	7-35
Figure 7-39	Bluff failure by a combination of marine, terrestrial, and seismic processes led to progressive undercutting of blufftop apartments at Capitola, California.	7-35
Figure 7-40	Longshore variations in long-term erosion rates, Delaware Atlantic shoreline.	7-37
Figure 7-41	Shoreline changes through time at a location approximately 1.5 miles south of Indian River Inlet, Delaware.	7-38
Figure 7-42	Seasonal fluctuations in beach width and elevation.	7-38
Figure 7-43	Flood protection offered by eroded dunes.	7-41
Figure 7-44	Hurricane Georges (1998). Damage to buildings landward of dune crossed by vehicle paths.	7-42
Figure 7-45	Ocean City Inlet, Maryland, was opened by a hurricane in 1933 and stabilized by jetties in 1934–35.	7-44
Figure 7-46	Buildings threatened by erosion at Ocean Shores, Washington.	7-45
Figure 7-47	July 1989 photograph of vacant lot owned by Lucas, Isle of Palms, South Carolina.	7-46
Figure 7-48	December 1997 photograph taken in the same area as Figure 7-47.	7-46
Figure 7-49	Historical shoreline changes in the vicinity of Lucas Lots.	7-47
Figure 7-50	Trapping of littoral sediments behind offshore breakwaters, Persque Isle, Pennsylvania.	7-48
Figure 7-51	Hurricane Fran (1996). Determination of localized scour from changes in sand color, texture, and bedding.	7-52

Figure 7-52 Hurricane Fran (1996). Extreme case of localized scour undermining a slab-on-grade house on Topsail Island, North Carolina. 7-52

Figure 7-53 Windblown sand drifting against coastal residences in Pacific City, Oregon. 7-54

Figure 7-54 0.2-sec spectral response acceleration – maximum earthquake ground motion (%g). 7-56

Figure 7-55 1.0-sec spectral response acceleration – maximum earthquake ground motion (%g). 7-58

Figure 7-56 Unstable coastal bluff at Beacon’s Beach, San Diego, California. 7-62

Figure 7-57 Landslide incidence in the coterminous United States. 7-64

Figure 7-58 Example of corrosion, and resulting failure, of metal connectors. 7-66

Figure 7-59 Hurricane Eloise, Bay County, Florida. Average damage per structure (in thousands of 1975 dollars) vs. distance from the Florida Coastal Construction Control Line. 7-69

Figure 7-60 BFE determination criteria for coastal hazard areas in the United States. 7-71

Figure 7-61 Procedural flowchart for defining coastal flood hazards. 7-73

Figure 7-62 Definition sketch for frontal dune reservoir. 7-75

Figure 7-63 Current FEMA treatment of dune retreat and dune removal. 7-76

Figure 7-64 Procedure recommended by this manual for calculating dune retreat profile. 7-77

Figure 7-65 Erosion hazard checklist. 7-82

Figure 7-66 Flowchart for estimating maximum likely flood hazards at a site over the life of a building or development. 7-83

Figure 7-67 Accounting for future shoreline erosion: shift the present-day profile landward (to account for long-term or inlet erosion), then apply the Primary Frontal Dune erosion assessment to estimate the lowest expected ground elevation at a site. 7-84

Chapter 8**Siting**

Figure 8-1	Evaluation of a coastal property.	8-2
Figure 8-2	Hurricane Opal (1995). Damage to new construction in a mapped A zone.	8-4
Figure 8-3	Example of coastal development well-suited to the land: deep lots, generous setbacks, and avoidance of dune areas should afford protection against erosion and flood events for years to come.	8-5
Figure 8-4	Increasingly, coastal residential structures are being planned and constructed as part of mixed-use developments, such as this marina/townhouse development.	8-5
Figure 8-5	Planning and site development guidelines for raw land.	8-6
Figure 8-6	View along a washed-out, shore-parallel road in Bay County, Florida, after Hurricane Opal.	8-7
Figure 8-7	Recommended lot layout.	8-8
Figure 8-8	Comparison of Nags Head, North Carolina, oceanfront lot layouts permitted before 1987 and post-1987 oceanfront lot requirements.	8-8
Figure 8-9	Shore-parallel roadways and associated utilities may be vulnerable to storm effects and erosion (upper). One alternative is to create lots and infrastructure without the shore-parallel road; install shutoff valves on water and sewer lines (lower).	8-9
Figure 8-10	Typical layout of “flag” lots or “key” lots, which are NOT RECOMMENDED for use along eroding shorelines (upper). Suggested alternative layout (lower).	8-10
Figure 8-11	Construction along this narrow, low-lying area of St. Johns County, Florida, is routinely subjected to coastal storm effects.	8-11
Figure 8-12	Lot landward of opening between dunes or obstructions may be more vulnerable to flooding and wave effects.	8-12
Figure 8-13	Coastal lot development scenarios.	8-13

Figure 8-14	Humbolt County, California, parcel fronting the Pacific Ocean.	8-14
Figure 8-15	Guidelines for siting buildings on existing lots.	8-16
Figure 8-16	This site near Malibu, California, is an example of a coastal building site subject to multiple hazards—storm waves and erosion, stream flooding and debris flows, and earthquakes.	8-18
Figure 8-17	Hurricane Hugo (1989). Damage to buildings sited close to an eroding shoreline at Garden City, South Carolina.	8-18
Figure 8-18	Damage at Bonita Beach, Florida, from June 1982 subtropical storm.	8-19
Figure 8-19	Siting and designing buildings to accommodate large trees is important for a variety of reasons.	8-20

Chapter 9

Financial and Insurance Implications

Figure 9-1	Basic benefit/cost model.	9-4
Figure 9-2	Comparison of FIA V-zone and A-zone depth-damage functions (no contents damage included).	9-10

Chapter 11

Determining Site-Specific Loads

Figure 11-1	Load determination flowchart.	11-2
Figure 11-2	Examples of tributary areas for different structural members.	11-5
Figure 11-3	Parameters that determine or are affected by flood depth.	11-7
Figure 11-4	Velocity vs. design stillwater flood depth in areas not subject to tsunamis.	11-11
Figure 11-5	Lateral flood force on a vertical component.	11-12
Figure 11-6	Vertical (buoyant) flood force.	11-13
Figure 11-7	Dynamic, static, and total pressure distributions against a vertical wall.	11-16

Figure 11-8	Water depth vs. wave height, and water depth vs. breaking wave force against a vertical wall (for Case 2, with stillwater behind the wall) for the 1-percent and 50-percent exceedance interval events.	11-17
Figure 11-9	Hydrodynamic loads on a building.	11-18
Figure 11-10	Determining drag coefficient from width-to-depth ratio.	11-20
Figure 11-11	Pile deflection vs. duration of impact (t) for alternative wood pile foundations.	11-25
Figure 11-12	Scour at vertical foundation member stopped by underlying scour-resistant stratum.	11-26
Figure 11-13	Plan view of site and building, with flood hazard zones.	11-31
Figure 11-14	Section A: Primary frontal dune will be lost during 100-year flood because dune reservoir is less than 1,100 ft ²	11-31
Figure 11-15	Building elevation and plan view of pile foundation.	11-32
Figure 11-16	Tsunami velocity vs. design stillwater depth.	11-36
Figure 11-17	Effect of wind on an enclosed building and a building with an opening.	11-38
Figure 11-18	Wind speed map.	11-40
Figure 11-19	Wind pressures on the MWFRS on a cross section of the case study building.	11-42
Figure 11-20	Wind pressures on the MWFRS.	11-43
Figure 11-21	Typical building connections.	11-44
Figure 11-22	Building elevation and plan view of roof.	11-45
Figure 11-23	Wind pressure zones for the MWFRS.	11-46
Figure 11-24	Wind pressure zones for components and cladding; most severe negative pressure coefficients shown.	11-47
Figure 11-25	Shear and overturning forces.	11-50
Figure 11-26	Gravity further deforms the out-of-plumb frame of the building.	11-50

Figure 11-27 Effect of seismic forces on supporting piles. 11-50

Figure 11-28 Building elevation and plan view of roof showing longitudinal shearwalls. 11-55

Figure 11-29 Side view of building in Figure 11-23. 11-59

Chapter 12

Designing the Building

Figure 12-1 Coastal construction design process. 12-1

Figure 12-2 Uplift. 12-5

Figure 12-3 Hurricane Andrew (1992), Dade County, Florida. Roof structure failure due to inadequate bracing. 12-6

Figure 12-4 Hurricane Andrew (1992), Dade County, Florida. Second-story wood framing (on first-story masonry). End gable and wall failure. 12-7

Figure 12-5 Hurricane Diana (1984). Uplift failure of a porch roof. 12-7

Figure 12-6 Hurricane Andrew (1992), Dade County, Florida. Openings in house protected with plywood panels. 12-8

Figure 12-7 Overturning. 12-9

Figure 12-8 Hurricane Fran (1996), North Carolina. House overturned by flood and wind forces. 12-10

Figure 12-9 Hurricane Fran (1996), North Carolina. Lightweight building (manufactured home) overturned by flood and wind forces. 12-10

Figure 12-10 Sliding failure. 12-11

Figure 12-11 Hurricane Fran (1996), North Carolina. Failure of a coastal A-zone building constructed on a masonry wall and slab-on-grade foundation. 12-12

Figure 12-12 Hurricane Fran (1996), North Carolina. Building pilings (circled) snapped at top. 12-12

Figure 12-13 Hurricane Fran (1996), North Carolina. Building that moved off its foundation. 12-13

Figure 12-14	Hurricane Fran (1996), North Carolina. Building collapse caused by the force of water flowing through an inlet created across Topsail Island during the storm.	12-14
Figure 12-15	Load path at southwest corner of case study building.	12-15
Figure 12-16	Roof plan of case study building.	12-15
Figure 12-17	Elevations of case study building.	12-16
Figure 12-18	Example of two-story platform framing on pile-and-beam foundation.	12-17
Figure 12-19	Two-story balloon framing on pile-and-beam foundation.	12-19
Figure 12-20	Typical post-and-beam framing.	12-20
Figure 12-21	Two-story masonry wall with wood floor and roof framing.	12-22
Figure 12-22	Uplift and gravity forces on the case study building.	12-27
Figure 12-23	Overtopping moment on the case study building.	12-29
Figure 12-24	Sliding forces on the case study building.	12-31
Figure 12-25	Link #1 – attachment of roof sheathing to roof framing.	12-33
Figure 12-26	Effective area of a roof sheathing fastener in the field.	12-33
Figure 12-27	Deflection of an unblocked edge sheathing panel with one missing field nail due to wind uplift loading (deflected shape scaled for perspective).	12-35
Figure 12-28	Nailing zones for roof sheathing in 120-mph peak gust wind zone for the case study building.	12-35
Figure 12-29	Hurricane Marilyn (1995), U.S. Virgin Islands. Gable-end failure caused by high winds.	12-37
Figure 12-30	Hurricane Marilyn (1995), U.S. Virgin Islands. Hip roof that survived high winds with little to no damage.	12-37
Figure 12-31	Link #2 – connection of roof framing to exterior wall.	12-38
Figure 12-32	Uplift force components on roof.	12-39

Figure 12-33 Uplift forces on the connection of the roof framing to the exterior wall for this case study example. 12-39

Figure 12-34 Uplift connections on hip roof. 12-41

Figure 12-35 Typical connection of truss to wood wall. 12-42

Figure 12-36 Typical connection of truss to wood wall. 12-42

Figure 12-37 Hurricane Andrew (1992), Dade County, Florida. These properly placed hurricane straps were cast into the concrete bond beams atop a reinforced masonry wall and wrapped over the roof trusses. 12-43

Figure 12-38 Link #3 – connection of top wall plate to wall stud. 12-44

Figure 12-39 Link #4 – connection of wall sheathing to window header. 12-45

Figure 12-40 Link #5 – connection of window header to exterior wall. 12-46

Figure 12-41 Line #5 – tributary area for wind force normal to wall. 12-46

Figure 12-42 Metal connector at window opening. 12-48

Figure 12-43 Link #6 – connection of wall to floor framing. 12-48

Figure 12-44 Shear force distribution from east wind at roof diaphragm. 12-49

Figure 12-45 Loads on south shearwall. 12-50

Figure 12-46 Shearwall holddown connector with bracket attached to a wood beam. 12-51

Figure 12-47 Shearwall holddown connector (without bracket to post) attached to concrete beam. 12-52

Figure 12-48 Load summary at Link #6. 12-54

Figure 12-49 Steel moment frame at large opening. 12-54

Figure 12-50 Link #7 – connection of floor framing to support beam. 12-55

Figure 12-51 Metal joist/beam connector. 12-56

Figure 12-52 Wood joist/beam connector. 12-56

Figure 12-53 Link #8 – connection of floor support beam to foundation. 12-57

Figure 12-54	Corner pile bracing to reduce pile cap rotation.	12-58
Figure 12-55	Single and double shear connections.	12-59
Figure 12-56	Uplift tributary area from hip roof to a single pile.	12-62
Figure 12-57	Deflected pile shape for an unbraced pile.	12-64
Figure 12-58	Pile installation methods.	12-69
Figure 12-59	Design method for reducing effective column length of a cantilever pile.	12-70
Figure 12-60	Column/pier on a spread footing.	12-71
Figure 12-61	Horizontal load diagram for columns/piers on spread footings.	12-73
Figure 12-62	Hurricane Andrew (1992), Dade County, Florida. Gable-end failure.	12-76
Figure 12-63	Gable-end bracing recommendations.	12-77
Figure 12-64	Grade beams.	12-78
Figure 12-65	Diagonal bracing.	12-78
Figure 12-66	Knee bracing.	12-79
Figure 12-67	Grade beam layout.	12-80
Figure 12-68	Force diagram for diagonal bracing.	12-82
Figure 12-69	Bolt layout for diagonal brace.	12-83
Figure 12-70	Knee brace placement and forces.	12-84
Figure 12-71	Hurricane Hugo (1989), South Carolina. Typical failure mode of breakaway wall beneath an elevated building—failure of the connection between the bottom plate of the wall and the floor of the enclosed area.	12-86
Figure 12-72	Hurricane Opal (1995), Florida. Utility penetrations prevented this breakaway wall from breaking away cleanly.	12-86
Figure 12-73	Lattice installed beneath an elevated house in a V zone.	12-87
Figure 12-74	Metal connectors.	12-88
Figure 12-75	Board connected to both the roof member and the top plate of the wall.	12-89

Figure 12-76 Top-plate-to-wall-stud connector. 12-90

Figure 12-77 Shearwall holddown connector. 12-91

Figure 12-78 Failure of overnotched pile. 12-93

Figure 12-79 Hurricane Fran (1996), North Carolina. Square wood pile failure at edge knot. 12-97

Figure 12-80 House being constructed with a steel frame on wooden piles. 12-98

Figure 12-81 Townhouse framing system. 12-99

Figure 12-82 Deck attachment scheme that minimizes penetration of the building envelope. 12-102

Figure 12-83 The fire-resistant walls and roof of this house helped it survive a wildfire while surrounding houses were destroyed. 12-104

Figure 12-84 Roof/wall flashing detail. 12-108

Figure 12-85 Window flashing detail. 12-108

Figure 12-86 Drip at door head and drip with hook at head. 12-111

Figure 12-87 Door shoe with drip and vinyl seal. 12-111

Figure 12-88 Neoprene door bottom sweep. 12-111

Figure 12-89 Automatic door bottom. 12-111

Figure 12-90 Interlocking threshold for doors with exit hardware. .. 12-111

Figure 12-91 Adjustable jamb/head weatherstripping. 12-112

Figure 12-92 Hurricane Georges (1998), Puerto Rico. Inadequate window frame attachment caused the window frame to be pulled out of the wall. 12-113

Figure 12-93 Hurricane Georges (1998), Puerto Rico. Window broken by windborne debris. 12-114

Figure 12-94 Protection of sealant with a stop. 12-116

Figure 12-95 Motor-driven rollup shutters. 12-117

Figure 12-96 Hurricane Georges (1998), Puerto Rico. Permanently installed shutter tracks. 12-118

Figure 12-97 Plywood “shutter” attachment on either wood-frame or masonry walls. 12-118

Figure 12-98 Hurricane Marilyn (1995), U.S. Virgin Islands. Shutters constructed of 2x4 lumber. 12-119

Figure 12-99	Eave detail for asphalt shingles.	12-124
Figure 12-100	Rake detail for asphalt shingles	12-125
Figure 12-101	Hip and ridge detail for asphalt and composition shingles.	12-125
Figure 12-102	These wire-tied tiles (installed over a concrete deck and attached with stainless steel clips at the perimeter rows) failed during Typhoon Paka (1997) in Guam.	12-129
Figure 12-103	Most of the tiles on this roof were nailed to batten strips.	12-130
Figure 12-104	These tiles were nailed to thin wood sheathing.	12-130
Figure 12-105	Northridge Earthquake, California. The tile in the center of this photograph slipped out from underneath the hip tiles.	12-131
Figure 12-106	Hurricane Marilyn (1995), U.S. Virgin Islands. The ridge flashing on this corrugated metal- panel roof was well attached, with a double row of closely spaced fasteners on each side of the ridge.	12-133
Figure 12-107	Loss of wood shingles on this North Carolina house during Hurricane Bertha (1996) was due to corrosion of fasteners.	12-135
Figure 12-108	Typhoon Paka (1997), Guam. 24-gauge coping attached with stainless steel concrete spikes at 12 inches o.c.	12-137
Figure 12-109	Continuous bar near the edge of flashing/ coping.	12-138
Figure 12-110	Mortar-faced extruded polystyrene over base flashing for wildfire protection.	12-139
Figure 12-111	Method for maintaining a continuous load path at the roof ridge by nailing roof sheathing.	12-140
Figure 12-112	Holes drilled in roof sheathing for ventilation— roof diaphragm action is maintained.	12-141
Figure 12-113	Typhoon Paka (1997), Guam. Stainless steel cables for strengthening fan cowlings and vent hoods.	12-144

Figure 12-114 Hurricane Georges (1998), U.S. Gulf Coast. Mechanical equipment damaged as a result of insufficient elevation. 12-145

Figure 12-115 Proper elevation of mechanical equipment in a floodprone area. 12-145

Figure 12-116 Elevated electric meter. 12-148

Figure 12-117 Electric meters and feed lines that failed during Hurricane Opal (1995). 12-148

Figure 12-118 Hurricane Marilyn (1995), U.S. Virgin Islands. Damage caused by dropped overhead service. 12-149

Figure 12-119 Hurricane Georges (1998), Puerto Rico. Concrete pylon used for overhead service mast. 12-149

Figure 12-120 Wood walkover construction. 12-155

Figure 12-121 Recommended contraction joint layout for frangible slab-on-grade below elevated building. 12-156

Figure 12-122 Storage building anchored with strap and ground anchor. 12-160

Chapter 13

Constructing the Building

Figure 13-1 Site layout. 13-3

Figure 13-2 Typical pile notching process. 13-4

Figure 13-3 Overnotched pile. 13-4

Figure 13-4 Properly notched pile. 13-5

Figure 13-5 Plan view of foundation showing techniques for squaring a building. 13-6

Figure 13-6 Damage caused by slope failure. 13-8

Figure 13-7 Typical wood-pile foundation. 13-9

Figure 13-8 Diagonal wood bracing in a wood-pile foundation. 13-12

Figure 13-9 Knee bracing in a wood-pile foundation. 13-13

Figure 13-10 Open masonry foundation. 13-16

Figure 13-11 Concrete foundation. 13-17

Figure 13-12 Concrete house. 13-18

Figure 13-13	Wood decay at the base of a post supported by concrete.	13-21
Figure 13-14	Minimizing the least dimension of wood contact surfaces.	13-22
Figure 13-15	Drip cut minimizes horizontal water movement along the bottom surface of a wood member.	13-24
Figure 13-16	Exposure of end grain in stair stringer cuts.	13-24
Figure 13-17	Deterioration in a notched stair stringer.	13-24
Figure 13-18	Alternative method of installing stair treads.	13-25
Figure 13-19	Hurricane Iniki (1992), Hawaii. Connector failure caused by insufficient nailing.	13-28
Figure 13-20	Reinforcement of overnotched piles.	13-29
Figure 13-21	Beam support at misaligned piles.	13-30
Figure 13-22	Proper pile notching for two-member and four-member beams.	13-30
Figure 13-23	Metal twist strap ties (circled).	13-31
Figure 13-24	Plywood web I-beams used as floor joists with metal brace used to keep the bottoms of the joists from twisting.	13-32
Figure 13-25	Acceptable locations for splices in multiple-member girders.	13-33
Figure 13-26	Using full-height sheathing improves transfer of shear.	13-35
Figure 13-27	Hurricane Andrew (1992), Florida. Roof sheathing found in debris.	13-39
Figure 13-28	Sheathing nails (circled) missed roof rafter in new construction.	13-39
Figure 13-29	Building damage from Hurricane Opal at Pensacola Beach, Florida.	13-45
Figure 13-30	Stair elevation system.	13-46
Figure 13-31	Recommendations for orientation of in-ground pools.	13-48
Figure 13-32	Cantilever floor framing for air-conditioning/heat pump compressor platform – plan view.	13-51

Figure 13-33 Cantilever floor framing for air-conditioning/
heat pump compressor platform – elevation view. 13-51

Figure 13-34 Wood-brace-supported air-conditioning/heat
pump compressor platform – plan view. 13-52

Figure 13-35 Wood-brace-supported air-conditioning/heat
pump compressor platform – elevation view. 13-52

Figure 13-36 Anchoring techniques for aboveground tanks. 13-55

Chapter 14

Maintaining the Building

Figure 14-1 Pile that appears acceptable from the outside
but that is decayed in the center. 14-1

Figure 14-2 Wood decay at the base of a post supported
by concrete. 14-4

Figure 14-3 Wood decay behind a metal beam connector. 14-4

Figure 14-4 Typhoon Paka (1997), Guam. Corrosion
observed in the bottom flange of a structural
steel roof support member. 14-7

Figure 14-5 Deteriorated wood sill plate. 14-11

Figure 14-6 Typical 1/4-inch bead of adhesive between
roof sheathing and roof rafter. 14-14

Figure 14-7 Garage door on south Florida house reinforced
with 2x4 wood girts and metal mullions. 14-14

Appendix G

**Examples of State and Community Coastal Erosion Studies
and Hazard Zone Maps**

Figure G-1 Key to examples of coastal erosion
databases and studies. G-2

Figure G-2 Examples of state and community coastal
hazard zone delineations. G-6

Figure G-3 Schematic representation of hazard zones
A through D in Texas coastal areas. G-8

Figure G-4 Coastal hazard zones for low-elevation and
high-elevation shorelines in Texas. G-9

Figure G-5 Delaware coastal hazard zones. G-10

Figure G-6	Coastal construction building zones in Florida.	G-11
Figure G-7	Criteria used to establish Florida’s Coastal Construction Control Line (CCCL).	G-12
Figure G-8	North Carolina Ocean Hazard Areas of Environmental Concern.	G-13
Figure G-9	Minimum setbacks in North Carolina Ocean Erodible Areas.	G-14
Figure G-10	Example of delineation between standard erosion zone and unstabilized inlet erosion zone, Isle of Palms, South Carolina.	G-16
Figure G-11	Example of South Carolina baseline location where seawall encroaches onto active beach—dashed line indicates natural beach/dune profile superimposed on actual profile.	G-16
Figure G-12	Map of Nags Head, North Carolina, showing incipient inlets and areas subject to hurricane flooding.	G-17
Figure G-13	Sample coastal hazard map, Broward County, Florida.	G-18
Figure G-14	Shoreline erosion risk assessment map, San Diego, California.	G-20
Figure G-15	Coastal erosion hazard and mitigation map, City of Dana Point, California.	G-21
Figure G-16	Generalized depiction of geologic hazards along a coastal sea cliff.	G-22
Figure G-17	Recommended coastal bluff setbacks.	G-23
Figure G-18	Sample coastal hazard map from New Jersey Coastal Storm Vulnerability Analysis.	G-25
Figure G-19	Sample shoreline change map showing average annual shoreline change and projected future shoreline locations.	G-27
Figure G-20	Yaquina Bay, Oregon, tsunami inundation map.	G-27
Figure G-21	Hazard classification used to determine Overall Hazard Assessment, Hawaii.	G-29

Figure G-22	Wildfire safety zone recommended by Oregon Department of Forestry.	G-30
Figure G-23	Variables used to calculate the Coastal Vulnerability Index.	G-30
Figure G-24	Distribution of low-, moderate-, and high-risk shorelines – Louisiana, Mississippi, Alabama, Florida, Georgia, and South Carolina.	G-31
Figure G-25	City of Seattle Landslide Critical Areas (hatched areas) and locations of some of the landslides that occurred during the December 1996–January 1997 storms.	G-33
Figure G-26	Texas Department of Insurance construction zones, Galveston County, Texas.	G-34

Appendix K

Galvanized Roofing Attachment

Figure K-1	Ridge flashing detail for galvanized metal roofing.	K-3
Figure K-2	Eave flashing detail for galvanized metal roofing.	K-4
Figure K-3	Rake flashing detail for galvanized metal roofing.	K-5

List of Tables

Chapter 4

Fundamentals

Table 4.1	Natural Hazard Probabilities During Periods of Various Lengths	4-6
-----------	--	-----

Chapter 5

Identifying and Evaluating Site Alternatives

Table 5.1	General Information Checklist	5-7
Table 5.2	Potential Sources of Supporting Information for Evaluating Coastal Property	5-10
Table 5.3	Selected State Disclosure Requirements and Ongoing Efforts to Require Hazard Disclosure	5-12

Chapter 6**Investigating Regulatory Requirements**

Table 6.1	Summary of NFIP Regulatory Requirements and Recommendations for Exceeding the Requirements	6-17
-----------	--	------

Chapter 7**Identifying Hazards**

Table 7.1	Saffir-Simpson Hurricane Scale	7-3
Table 7.2	Mean Return Periods (in Years) for Landfall or Nearby Passage of Tropical Cyclones	7-6
Table 7.3	Modified Classification for Northeasters	7-7
Table 7.4	Areas Subject to Tsunami Events	7-11
Table 7.5	FEMA Coastal Erosion Study Areas	7-51
Table 7.6	Modified Mercalli Earthquake Intensity Scale	7-55
Table 7.7	FIS Model/Procedure Selection by Shoreline Type – Atlantic and Gulf of Mexico Coasts	7-72

Chapter 9**Financial and Insurance Implications**

Table 9.1	Examples of Flood and Wind Mitigation Measures	9-3
Table 9.2	Default Wind Damage as a Percent of Building Value	9-6
Table 9.3	FIA Depth-Structure Damage Data for V-Zone Buildings (Damage in Percent of Building Replacement Value)	9-8
Table 9.4	FIA Depth-Structure Damage Data for A-Zone Buildings (Damage in Percent of Building Replacement Value)	9-9
Table 9.5	Sample NFIP Flood Insurance Premiums for Buildings in A Zones	9-17
Table 9.6	Sample NFIP Flood Insurance Premiums for Buildings in V Zones – With and Without Obstructions Below the Lowest Floor	9-17

Chapter 11**Determining Site-Specific Loads**

Table 11.1	Value of Dynamic Pressure Coefficient, C_p , as a Function of Probability of Exceedance	11-16
Table 11.2	Drag Coefficients for Ratios of Width to Depth (w/d_s) and Width to Height (w/h)	11-20
Table 11.3	Impact Durations, t , for Use in Formula 11.9	11-25
Table 11.4	Scour Factor for Flow Angle of Attack, K	11-28
Table 11.5	Local Scour Depth vs. Soil Type	11-28
Table 11.6	Selection of Flood Load Combinations for Design	11-29
Table 11.7	Summary of Wind Pressures (p) on the MWFRS	11-46
Table 11.8	Summary of Wind Pressures for Components and Cladding	11-47

Chapter 12**Designing the Building**

Table 12.1	Wood Products Used for Structural Frame Components	12-23
Table 12.2	Alternatives to Wood Products for Structural Frame Components	12-24
Table 12.3	Building Layout and Impacts on Natural Hazard Design	12-25
Table 12.4	Building Areas Affected by Wind Hazard for the Case Study Building When Primary Wind Direction is From the East	12-26
Table 12.5	Nail Spacing Required in Field for 1/2-Inch Roof Sheathing Using Various Size Nails at 120 mph (3-sec peak gust) at Link #1 for the Case Study Building	12-34
Table 12.6	Nailing Requirements for the Case Study Roof – 120-mph, 3-sec Peak Gust Wind, 1/2-Inch-Thick Roof Sheathing With 8d Common Nails	12-36
Table 12.7	Uplift Forces at Each Connection in Hip Roof for the Case Study Example	12-40

Table 12.8	Shear and Withdrawal Resistance Provided by 16d Box Nails	12-47
Table 12.9	Allowable Capacities of Wood Piles (lb) for the Case Study Example Only, Based on End Bearing and Frictional Resistance	12-62
Table 12.10	Values of n_h , Modulus of Subgrade Reaction	12-64
Table 12.11	Maximum Unbraced Lengths of Various Pile Materials for the 989-lb Lateral Load	12-66
Table 12.12	Pile Material Selection	12-67
Table 12.13	Selection of Pile Installation Method	12-69
Table 12.14	Nail Capacities for Link #3	12-90
Table 12.15	General Guidance for Selection of Materials – Advantages and Special Considerations	12-94
Table 12.16	Selection of Materials for Use in Foundation Elements Below the DFE – Advantages and Special Considerations	12-96

Chapter 13

Constructing the Building

Table 13.1	Soil Type Definitions Based on USDA Unified Soil Classification System	13-7
Table 13.2	Engineering Properties of Soil Types Classified by USDA	13-7
Table 13.3	Foundation Inspection Points	13-27
Table 13.4	Floor Framing Inspection Points	13-34
Table 13.5	Wall Inspection Points	13-37
Table 13.6	Roof Frame Inspection Points	13-40
Table 13.7	Building Envelope Inspection Points	13-43

Chapter 14

Maintaining the Building

Table 14.1	Maintenance Inspection Checklist	14-2
Table 14.2	Life Expectancies for Elements of Coastal Buildings	14-12
Table 14.3	Cost Estimates for Retrofitting	14-15

Appendix K

Galvanized Roofing Attachment

Table K.1 Complete Load Path Fastener Options K-2

List of Formulas

Chapter 11

Determining Site-Specific Loads

Formula 11.1 Design Stillwater Flood Depth 11-8

Formula 11.2 Design Flood Velocity 11-10

Formula 11.3 Lateral Hydrostatic Load 11-12

Formula 11.4 Vertical (Buoyant) Hydrostatic Force 11-13

Formula 11.5 Breaking Wave Load on Vertical Piles 11-15

Formula 11.6 Breaking Wave Loads on Vertical Walls 11-16

Formula 11.7 Hydrodynamic Load From Flood Flows
Moving at Less Than 10 ft/sec 11-19

Formula 11.8 Hydrodynamic Load From Flood Flows
Moving at Greater Than 10 ft/sec 11-21

Formula 11.9 Debris Impact Load 11-23

Formula 11.10a Localized Scour Around Vertical Pile
(Non-Tsunami Condition) 11-27

Formula 11.10b Localized Scour Around Vertical Enclosure
(Non-Tsunami Condition) 11-27

Formula 11.11 Seismic Base Shear by the Simplified
Analysis Procedure 11-52

Formula 11.12 Vertical Distribution of Seismic Forces 11-54

Chapter 12

Designing the Building

Formula 12.1 Frictional Resistance of Soil 12-13

Formula 12.2 Net Uplift Force 12-28

Formula 12.3 Overturning Moment 12-30

Formula 12.4	Sliding Resistance of Foundation Walls and Footing	12-32
Formula 12.5	Determining Uplift Forces at Each Connection in Hip Roof	12-40
Formula 12.6	Ultimate Compression Capacity of a Single Pile (Developed by End Bearing and Frictional Resistance)	12-60
Formula 12.7	Ultimate Tension Capacity of a Single Pile (Developed by Frictional Resistance)	12-61
Formula 12.8	Combined Axial and Bending Stresses	12-62
Formula 12.9	Determination of Actual Bending Stress	12-63
Formula 12.10	Effective Length of Unbraced Pile	12-64
Formula 12.11	Determination of Square Footing Size for Gravity Loads for the Case Study Building	12-72
Formula 12.12	Determination of Soil Pressure for the Case Study Building	12-73

Chapter 13

Constructing the Building

Formula 13.1	Pile Driving Resistance for Drop Hammer Pile Drivers	13-10
--------------	--	-------

Acknowledgments

FEMA acknowledges the following organizations and individuals for their contributions in the preparation of this manual. Many of the individuals listed here served as members of the Technical Review Committee and Working Groups established by FEMA to investigate issues discussed in this manual. Others who were contacted and provided assistance during the preparation of this manual are listed in Appendix A (in Volume III).

Organizations

Greenhorne & O'Mara, Inc.
American Institute of Architects
American Society of Civil Engineers
American Wood Council
Association of State Floodplain Managers
Florida Department of Environmental Protection
Institute for Business & Home Safety
National Association of Home Builders
National Concrete Masonry Association
New Jersey Department of Environmental Protection
PBS&J
Portland Cement Association
Southern Building Code Congress International, Inc.
Texas Tech University
Wiss, Janney, Elstner & Associates
URS, Greiner, Woodward-Clyde

Individuals

Christopher Jones, P. E., Charlottesville, VA
Don Beaton, Chief, Underwriting Branch, FEMA, Federal Insurance Administration, Washington, DC
Doug Bellomo, Hydraulic Engineer, FEMA, Mitigation Directorate, Washington, DC

Eric Berman, Civil Engineer, FEMA Region V, Mitigation Division, Chicago, IL

Bruce Bortz, Ph.D., Town of Nags Head, NC

Bob Bruce, Wiss, Janney, Elstner & Associates, Emeryville, CA

Matt Campbell, Program Specialist, FEMA, Mitigation Directorate, Washington, DC

Marvin Cantor, American Institute of Architects, Fairfax, VA

Gene Chalecki, Florida Department of Environmental Protection, Bureau of Beaches and Coastal Systems, Tallahassee, FL

Mary Chang, FEMA, Federal Insurance Administration, Washington, DC

James Cohen, P. E., Pennington, NJ

Mary Colvin, Natural Hazards Program Specialist, FEMA Region II, Mitigation Division, New York, NY

Jay Crandell, National Association of Home Builders Research Center, Upper Marlboro, MD

Mark Crowell, Physical Scientist, FEMA, Mitigation Directorate, Washington, DC

Dan Deegan, URS, Greiner, Woodward-Clyde, Norcross, GA

Vincent DiCamillo, PBS&J, Bowie, MD

Brad Douglas, American Forest & Paper Association, Washington, DC

Robert Durrin, Emergency Management Specialist, FEMA Region IV, Mitigation Division, Atlanta, GA

Lesley Ewing, California Coastal Commission, San Francisco, CA

Ken Ford, National Association of Home Builders, Washington, DC

Lois Forster, Program Specialist, FEMA, Mitigation Directorate, Washington, DC

John Gambel, Civil Engineer, FEMA, Mitigation Directorate, Washington, DC

Bret Gates, Program Specialist, FEMA, Mitigation Directorate, Washington, DC

James Good, Professor and Coastal Resources Specialist, Oregon State University, Corvallis, OR

Dennis Graber, Director of Technical Publications, National Concrete Masonry Association, Herndon, VA

Larry Hallada, The Insurance Professionals, Selbyville, DE

Darryl Hatheway, Senior Coastal Scientist, Dewberry & Davis, Fairfax, VA

Mark Hogan, National Concrete Masonry Association, Herndon, VA

Barry Johnson, Southern Building Code Congress International, Birmingham, AL

Philip Keillor, Coastal Engineering Specialist, University of Wisconsin Sea Grant Institute, Madison, WI

Do Kim, Director of Engineering, Institute for Business and Home Safety, Boston, MA

David Kriebel, Ph.D., P. E., United States Naval Academy, Annapolis, MD

Margret Lawless, Director, Program Development & Coordination Division, FEMA, Mitigation Directorate, Washington, DC

Elizabeth Lemersal, Physical Scientist, FEMA, Mitigation Directorate, Washington, DC

Ray Lenaburg, Civil Engineer, FEMA Region IX, Mitigation Division, San Francisco, CA

William Lesser, Program Specialist, FEMA, Mitigation Directorate, Washington, DC

Howard Leikin, Chief Actuary, FEMA, Federal Insurance Administration, Washington, DC

Phil Line, Manager, Engineering Research, American Wood Council, American Forest & Paper Association, Washington, DC

Brad Loar, Sr. Emergency Program Specialist, FEMA Region IV, Mitigation Division, Atlanta, GA

Sharon Loper, Outreach Specialist, FEMA, Mitigation Directorate, Washington, DC

Ralph Maffei, Insurance Services Office, New York, NY

Mike Mahoney, Geophysicist, FEMA, Mitigation Directorate, Washington, DC

Mark Mauriello, New Jersey Department of Environmental Protection, Bureau of Coastal Regulation, Trenton, NJ

Patty McDaniel, Boardwalk Builders, Rehoboth Beach, DE

Jim McDonald, Director, Institute for Disaster Research, Texas Tech University, Lubbock TX

Kishor Mehta, Director, Wind Engineering Research Center, Texas Tech University, Lubbock, TX

Jim Messersmith, Portland Cement Association, Rockville, MD

Clifford Oliver, Chief, Program, Policy, and Assessment Branch, FEMA, Mitigation Directorate, Washington, DC

Frank Pagano, Director, Mitigation Division, FEMA Region VI, Denton, TX

William Parrish, State Floodplain Manager and NFIP Coordinator, Maryland Department of the Environment, Annapolis MD

Robert Reynolds, Training Officer, FEMA Region II, New York, NY

Mike Robinson, Program Specialist, FEMA, Mitigation Directorate, Washington, DC

Spencer Rogers, Jr., Coastal Construction and Erosion Specialist, North Carolina Sea Grant, Wilmington, NC

Cecelia Rosenberg, Physical Scientist, FEMA, Mitigation Directorate, Washington, DC

Jim Self, Florida Windstorm Underwriting Association, Jacksonville, FL

Gary Sepulvado, Emergency Management Specialist, FEMA, Mitigation Directorate, Washington, DC

Tom Smith, TlSmith Consulting, Inc., Rockton, IL

Jeanine Stevens, Office of Ocean and Coastal Resource Management, National Oceanic and Atmospheric Administration, Washington, DC

Paul Tertell, Civil Engineer, FEMA, Mitigation Directorate, Washington, DC

Mark Vieira, Engineer, FEMA Region IV, Mitigation Division, Atlanta, GA

Rick Vognild, Southern Building Code Congress International, Birmingham, AL

French Wetmore, French & Associates, Ltd., Park Forest, IL

Acronyms and Abbreviations

The following are lists of acronyms and abbreviations used in this manual and the terms they represent.

Acronyms

AEC	Area of Environmental Concern
AFPA	American Forest and Paper Association
AIA	American Institute of Architects
AIRAC	All-Industry Research Advisory Council
APA	American Planning Association
ASCE	American Society of Civil Engineers
ASD	allowable stress design
ASTM	American Society for Testing and Materials
AWPA	American Wood Preservers Association
BCEGS	Building Code Effectiveness Grading Schedule
BFE	Base Flood Elevation
BOCA	Building Officials and Code Administrators International, Inc.
BPAT	Building Performance Assessment Team
BUR	built-up roof
CABO	Council of American Building Officials
CAFRA	Coastal Area Facility Review Act
CAMA	Coastal Area Management Act
CBIA	Coastal Barrier Improvement Act
CBRA	Coastal Barrier Resources Act
CBRS	Coastal Barrier Resources System
CCCL	Coastal Construction Control Line (Florida)
CEA	California Earthquake Authority
CFR	Code of Federal Regulations
CMU	concrete masonry unit
CRS	Community Rating System
CZM	coastal zone management
DFE	design flood elevation

EIFS	exterior insulating finishing system
FBBCS	Florida Bureau of Beaches and Coastal Systems
FEMA	Federal Emergency Management Agency
FIA	Federal Insurance Administration
FIRM	Flood Insurance Rate Map
FIS	Flood Insurance Study
FS	factor of safety
GLSDRS	Great Lakes Storm Damage Reporting System (USACE)
HO	homeowner
HVAC	heating, ventilating, and cooling
IBC	International Building Code
IBHS	Institute for Business & Home Safety
ICBO	International Conference of Building Officials
ICC	International Code Council
IRC	International Residential Code
ISO	Insurance Services Office
LRFD	load resistance factor design
LVL	Laminated-Veneer Lumber
MHW	mean high water
MHHW	mean higher high water
MLW	mean low water
MLLW	mean lower low water
MSL	mean sea level
MWFRS	main wind force resisting system
NAHB	National Association of Home Builders
NAS	National Academy of Sciences
NAVD	North American Vertical Datum
NCRS	Natural Resources Conservation Service (formerly Soil Conservation Service)
NEHRP	National Earthquake Hazards Reduction Program
NFIP	National Flood Insurance Program
NGVD	National Geodetic Vertical Datum
NOAA	National Oceanic and Atmospheric Administration
NRCA	National Roofing Contractors Association

NRCS	Natural Resources Conservation Service
NSPE	National Society of Professional Engineers
NWS	National Weather Service
OCRM	Office of Ocean and Coastal Resource Management (National Ocean Service)
OPA	Otherwise Protected Area
OSB	oriented strand board
PSL	parallel-strand lumber
SBC	Standard Building Code
SEAOC	Structural Engineers Association of California
SFHA	Special Flood Hazard Area
SFIP	Standard Flood Insurance Policy
SBCCI	Southern Building Code Congress International
SPF	sprayed polyurethane foam
SWL	stillwater level
UBC	Uniform Building Code
USACE	U.S. Army Corps of Engineers
USGS	U.S. Geological Survey
Wind-MAP	Windstorm Market Assistance Program (New Jersey)

Abbreviations for Units of Measure and Technical Terms

C_d	drag coefficient
C_p	dynamic pressure coefficient
C_{pe}	external wind pressure coefficient
cos	cosine
D	dead load
d_s	design stillwater flood depth
dia	diameter
E	earthquake load
E_{sw}	design stillwater elevation
F	load due to fluids with well-defined pressures and maximum heights
F_a	flood load
F_{brkp}	breaking wave load on pile
F_{brkw}	breaking wave load on wall
F_{dyn}	hydrodynamic load

F_i	debris impact load
F_{sta}	hydrostatic load
ft	foot, feet
ft ²	square foot, square feet
ft/sec	feet per second
g	gravitational constant
G	wind gust effect factor
H	loads due to weight and lateral pressures or soil and water in soil
H_b	breaking wave height
in	inch, inches
lb	pound, pounds
lb/ft ³	pounds per cubic foot
L	live load
L_r	roof live load
m	meter, meters
mph	miles per hour
o.c.	on center
p	design wind pressure
psf	pounds per square foot
psi	pounds per square inch
R	response modification coefficient (of a structural system)
R	rain load
S	snow load
sec	second
S_{max}	maximum depth of scour
t	time
t	duration of impact
T	self-straining load
V	velocity
Vol	volume of water displaced by a submerged object
w	weight (of an object)
W	effective seismic weight (of a building)
W	wind load
ρ	mass density of fluid
γ	specific weight of water

Metrification

FEMA is committed to the Federal Government's transition to the metric system; however, English units remain the standard of practice for residential construction. Therefore, all measurements in this manual are presented in English units. Because the metric system may eventually become the standard of measurement in the United States, approximate metric conversions are presented below to promote familiarity with that system.

A critical component of unit conversion is rounding. Designers should check to ensure that rounding does not exceed allowable tolerances for design or fabrication.

Metric Conversion Factors

Quantity	To Change English Units	To Metric Units	Multiply English Units By:
Length	inch (in)	millimeter (mm)	25.4000
	foot (ft)	meter (m)	0.3048
	mile (mi)	kilometer (km)	1.6093
Area	square foot (ft ²)	square meter (m ²)	0.0929
	acre (a)	square meter (m ²)	4,046.8564
Volume	gallon (gal)	liter (L)	3.7854
	cubic foot (ft ³)	cubic meters (m ³)	0.0283
Pressure	psf (lb/ft ²)	Pa	47.8803
	psi (lb/in ²)	kPa	6.8947
Weight	pound (lb)	kilogram (kg)	0.4536
Flow	cfs (ft ³ /sec)	lps	28.3168
Velocity	fps (ft/sec)	mps	0.3048
	mph	kph	1.6093