


Hairline seperation

2024/06/11 08:59:34

No gutters or downspouts.

Brick Veneer that has been repointed and sealed.

Mold to be removed.

A photograph of a brick veneer wall above a concrete foundation. The bricks are light-colored with some reddish-brown staining. A concrete foundation runs horizontally across the middle of the image. Two white arrows point to specific areas: one points to a crack in the brickwork, and the other points to a crack in the concrete foundation. The foreground is filled with green grass. A window is visible in the upper right corner.

Hairline crack in  
Brick Veneer

Hairline seperation

2024/06/11 09:01:17