

Ridge beam cracked and twisted pulling from roof rafter

