4. Select Appeal Type/Deficiency Type/Sub-Type: (cont.)

B) ☒ Accessibility

- ☐ General Accessibility
- ☒ Accessible Routes
- ☐ Parking
- ☐ Toilet Rooms
- ☐ Bathing Rooms
- ☐ Reach Range
- ☐ Clear Floor Space
- ☐ Changes in Level
- ☐ Doors
- ☐ Ramps
- ☐ Stairs
- ☐ Handrails
- ☐ Other

C) ☐ Subsequent Appeal

D) ☐ Product Evaluation

E) ☐ Building Code Equivalencies for Industrialized Buildings

F) ☐ Smoke Generation and/or Timed Egress Flow Analysis

5. Description of Deficiency: The code requires an exit directly to the outside for day care ages two and a half and under.

Figure 903.2 Fire Protection Systems threshold - Fire area > 12,000 sq. ft. or below level of exit discharge or each classroom has exterior door at grade.

6. Proposed Equivalency: This building has an existing fully functional sprinkler system and fire alarm that will remain in place.

This layout provides for the infants to have a exit of discharge directly outside at grade.