WINDOW SCHEDULE 1

WINDOW NUMBER	TYPE	NEW / EXIST	LEVEL	MATERIAL	Description	SIZE		DETAILS			GLAZING		REMARKS
						W	H	SILL	JAMB	HEAD			
01 CANAL STREET ELEVATION (SOUTH)													
A1	A	NEW	02 LOGE LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A2	A	NEW	02 LOGE LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A3	A	NEW	02 LOGE LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A4	A	NEW	02 LOGE LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A15	A	NEW	03 MIDDLE BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A16	A	NEW	03 MIDDLE BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A17	A	NEW	03 MIDDLE BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A18	A	NEW	03 MIDDLE BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A29	A	NEW	04 UPPER BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A30	A	NEW	04 UPPER BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A31	A	NEW	04 UPPER BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A32	A	NEW	04 UPPER BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A42	A	NEW	04 UPPER BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
02 BASIN STREET (WEST)													
H1	H	EXIST.	01 ORCHESTRA LEVEL			3'-4"	3'-0"						REPAIR AS REQUIRED
N1	N	EXIST.	01 ORCHESTRA LEVEL			3'-2 1/2"	2'-8"	5/A-5.22	6/A-5.22	7/A-5.22			REPAIR / REPLACE BROKEN MISSING HARDWARE IN KIND.HARDWARE SHALL BE APPROVED BY ARCHITECT
N2	N	EXIST.	01 ORCHESTRA LEVEL			3'-2 1/2"	2'-8"	5/A-5.22	6/A-5.22	7/A-5.22			REPAIR / REPLACE BROKEN MISSING HARDWARE IN KIND.HARDWARE SHALL BE APPROVED BY ARCHITECT
F1	F	EXIST.	01.5 BACK OF HOUSE LEVEL 2			3'-2 1/2"	4'-11"	1/A-5.22	2/A-5.22	3/A-5.22			REPLACE/ REPAIR INTERIOR SILL, UPPER SASH, BROKEN OR MISSING HARDWARE. HARDWARE SHALL APPROVED BY THE ARCHITECT.
F2	F	EXIST.	01.5 BACK OF HOUSE LEVEL 2			3'-2 1/2"	4'-11"	1/A-5.22	2/A-5.22	3/A-5.22			REPAIR / REPLACE BROKEN MISSING HARDWARE IN KIND.HARDWARE SHALL BE APPROVED BY ARCHITECT
F3	F	EXIST.	01.5 BACK OF HOUSE LEVEL 2			3'-2 1/2"	4'-11"	1/A-5.22	2/A-5.22	3/A-5.22			REPAIR / REPLACE CASING, BROKEN MISSING HARDWARE IN KIND.HARDWARE SHALL BE APPROVED BY ARCHITECT
F4	F	EXIST.	01.5 BACK OF HOUSE LEVEL 2			3'-2 1/2"	4'-11"	1/A-5.22	2/A-5.22	3/A-5.22			REPAIR / REPLACE UPPER SASH, BROKEN MISSING HARDWARE IN KIND.HARDWARE SHALL BE APPROVED BY ARCHITECT
G1	G	EXIST.	02 LOGE LEVEL			3'-2 1/2"	5'-3"	1/A-5.22	2/A-5.22	3/A-5.22			REPAIR / REPLACE INTERIOR SILL, LOWER SASH, BROKEN MISSING HARDWARE IN KIND.HARDWARE SHALL BE APPROVED BY ARCHITECT
G2	G	EXIST.	02 LOGE LEVEL			3'-2 1/2"	5'-3"	1/A-5.22	2/A-5.22	3/A-5.22			REPAIR / REPLACE BROKEN MISSING HARDWARE IN KIND.HARDWARE SHALL BE APPROVED BY ARCHITECT
G3	G	EXIST.	02 LOGE LEVEL			3'-2 1/2"	5'-3"	1/A-5.22	2/A-5.22	3/A-5.22		NEW	REPAIR / REPLACE CASING, BROKEN MISSING HARDWARE IN KIND.HARDWARE SHALL BE APPROVED BY ARCHITECT
G4	G	EXIST.	02 LOGE LEVEL			3'-2 1/2"	5'-3"	1/A-5.22	2/A-5.22	3/A-5.22			REPLACE/ REPAIR INTERIOR SILL, CASING, BROKEN OR MISSING HARDWARE. HARDWARE SHALL APPROVED BY THE ARCHITECT.
G19	C	EXIST.	02 LOGE LEVEL			1'-8"	5'-8"	1/A-5.22	2/A-5.22	3/A-5.22			REPAIR / REPLACE INTERIOR SILL, LOWER SASH, BROKEN MISSING HARDWARE IN KIND.HARDWARE SHALL BE APPROVED BY ARCHITECT
G10	G	EXIST.	03 MIDDLE BALCONY LEVEL			3'-2 1/2"	5'-3"	1/A-5.22	2/A-5.22	3/A-5.22			REPAIR / REPLACE BROKEN MISSING HARDWARE IN KIND.HARDWARE SHALL BE APPROVED BY ARCHITECT
G11	G	EXIST.	03 MIDDLE BALCONY LEVEL			3'-2 1/2"	5'-3"	1/A-5.22	2/A-5.22	3/A-5.22			REPAIR / REPLACE BROKEN MISSING HARDWARE IN KIND.HARDWARE SHALL BE APPROVED BY ARCHITECT
G12	G	EXIST.	03 MIDDLE BALCONY LEVEL			3'-2 1/2"	5'-3"	1/A-5.22	2/A-5.22	3/A-5.22			REPAIR / REPLACE CASING, BROKEN MISSING HARDWARE IN KIND.HARDWARE SHALL BE APPROVED BY ARCHITECT
G13	G	EXIST.	03 MIDDLE BALCONY LEVEL			3'-2 1/2"	5'-3"	1/A-5.22	2/A-5.22	3/A-5.22			REPAIR / REPLACE BROKEN MISSING HARDWARE IN KIND.HARDWARE SHALL BE APPROVED BY ARCHITECT
04 RAMPART STREET ELEVATION (EAST)													
D1	D	EXIST.	01.5 BACK OF HOUSE LEVEL 2			3'-2 1/2"	1'-7"	13/A-5.22	14/A-5.22	15/A-5.22			REPAIR / REPLACE BROKEN MISSING HARDWARE IN KIND.HARDWARE SHALL BE APPROVED BY ARCHITECT
E1	E	EXIST.	01.5 BACK OF HOUSE LEVEL 2			3'-0"	1'-7"	13/A-5.22	14/A-5.22	15/A-5.22			
E2	E	EXIST.	01.5 BACK OF HOUSE LEVEL 2			3'-0"	1'-7"	13/A-5.22	14/A-5.22	15/A-5.22			REPLACE MISSING HARDWARE, LEFY AND RIGHT CORD AND HANDLES
E3	E	EXIST.	01.5 BACK OF HOUSE LEVEL 2			3'-0"	1'-7"	13/A-5.22	14/A-5.22	15/A-5.22			REPLACE BOTTOM CASING AND HARDWARES
E4	E	EXIST.	01.5 BACK OF HOUSE LEVEL 2			3'-0"	1'-7"	13/A-5.22	14/A-5.22	15/A-5.22			REPLACE BOTTOM CASING AND HARDWARES
E5	E	EXIST.	01.5 BACK OF HOUSE LEVEL 2			3'-0"	1'-7"	13/A-5.22	14/A-5.22	15/A-5.22			REPAIR / REPLACE BROKEN MISSING HARDWARE IN KIND.HARDWARE SHALL BE APPROVED BY ARCHITECT
E6	E	EXIST.	01.5 BACK OF HOUSE LEVEL 2			3'-0"	1'-7"	13/A-5.22	14/A-5.22	15/A-5.22			REPAIR / REPLACE BROKEN MISSING HARDWARE IN KIND.HARDWARE SHALL BE APPROVED BY ARCHITECT
A5	A	NEW	02 LOGE LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A6	A	NEW	02 LOGE LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A7	A	NEW	02 LOGE LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A8	A	NEW	02 LOGE LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A9	A	NEW	02 LOGE LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A10	A	NEW	02 LOGE LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A11	A	NEW	02 LOGE LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A12	A	NEW	02 LOGE LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A13	A	NEW	02 LOGE LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A14	A	NEW	02 LOGE LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
B1	B	NEW	02 LOGE LEVEL	CLAD		2'-10"	4'-4"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
B2	B	NEW	02 LOGE LEVEL	CLAD		2'-10"	4'-4"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
C1	C	EXIST.	02 LOGE LEVEL			1'-8"	5'-8"						REPAIR AS REQUIRED
C2	C	EXIST.	02 LOGE LEVEL			1'-8"	5'-8"						REPAIR AS REQUIRED
C3	C	EXIST.	02 LOGE LEVEL			1'-8"	5'-8"						REPAIR AS REQUIRED
G5	G	EXIST.	02 LOGE LEVEL			3'-2 1/2"	4'-6"	9/A-5.22	11/A-5.22	12/A-5.22		BLACK FILM	REPAIR AS REQUIRED
G6	G	EXIST.	02 LOGE LEVEL			3'-2 1/2"	4'-6"	10/A-5.22	11/A-5.22	12/A-5.22		BLACK FILM	REPLACE HANDLES, TOP CASING AND RIGHT AND LEFT CORD
G7	G	EXIST.	02 LOGE LEVEL			3'-2 1/2"	4'-6"	10/A-5.22	11/A-5.22	12/A-5.22		BLACK FILM	REPLACE MISSING HARDWARE, LEFT CORD AND HANDLES
G8	G	EXIST.	02 LOGE LEVEL			3'-2 1/2"	4'-6"	10/A-5.22	11/A-5.22	12/A-5.22		BLACK FILM	REPLACE MISSING HARDWARE, LEFT CORD AND HANDLES
G9	G	EXIST.	02 LOGE LEVEL			3'-2 1/2"	4'-6"	10/A-5.22	11/A-5.22	12/A-5.22		BLACK FILM	REPLACE MISSING HARDWARE, LEFT CORD AND HANDLES
A19	A	NEW	03 MIDDLE BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A20	A	NEW	03 MIDDLE BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A21	A	NEW	03 MIDDLE BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A22	A	NEW	03 MIDDLE BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A23	A	NEW	03 MIDDLE BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A24	A	NEW	03 MIDDLE BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A25	A	NEW	03 MIDDLE BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A26	A	NEW	03 MIDDLE BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A27	A	NEW	03 MIDDLE BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
A28	A	NEW	03 MIDDLE BALCONY LEVEL	CLAD		3'-10 1/2"	6'-3"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
B3	B	NEW	03 MIDDLE BALCONY LEVEL	CLAD		2'-10"	4'-4"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
B4	B	NEW	03 MIDDLE BALCONY LEVEL	CLAD		2'-10"	4'-4"	17/A-5.22	18/A-5.22	19/A-5.22	GL-4		NEW WINDOW TO MATCH HISTORIC PROFILE IN EXISTING HOTEL BUILDING. PTD, TYP. WINDOW SHALL BE APPROVED BY ARCHITECT
G14	G	EXIST.	03 MIDDLE BALCONY LEVEL			3'-2 1/2"	4'-6"	9/A-5.22	11/A-5.22	12/A-5.22		BLACK FILM	REPLACE SILL, MISSING HARDWARE, CORDS AND HANDLES
G15	G	EXIST.	03 MIDDLE BALCONY LEVEL			3'-2 1/2"	4'-6"	10/A-5.22	11/A-5.22	12/A-5.22		BLACK FILM	REPLACE MISSING HARDWARE, RIGHT CORD AND HANDLES
G16	G	EXIST.	03 MIDDLE BALCONY LEVEL			3'-2 1/2"	4'-6"	10/A-5.22	11/A-5.22	12/A-5.22		BLACK FILM	REPLACE MISSING HARDWARE, LEFT CORD AND HANDLES
G17	G	EXIST.	03 MIDDLE BALCONY LEVEL			3'-2 1/2"	4'-6"	10/A-5.22	11/A-5.22	12/A-5.22		BLACK FILM	REPLACE MISSING HARDWARE AND HANDLES
G18	G	EXIST.	03 MIDDLE BALCONY LEVEL			3'-2 1/2"	4'-6"	10/A-5.22	11/A-5.22	12/A-5.22		BLACK FILM	REPLACE MISSING HARDWARE, LEFY AND RIGHT CORD AND HANDLES

THE SAENGER THEATRE RENEWAL PROJECT

142 North Rampart Street
New Orleans, LA

Client
Saenger Theatre Redevelopment Company
1800 Post Oak Boulevard, 6
Boulevard Place, Suite 450,
Houston, TX 77056

Architect
MARTINEZ+JOHNSON
ARCHITECTURE
1412 Eye St., NW
Washington, DC 20005
202.333.4480

Structural Engineer
Lundy & Franke Engineering, Inc.
549 Heimer Road, San
Antonio, TX 78232
210.979.7900

Theatre Consultant
Schuler Shook
123 Third Street North #210,
Minneapolis, MN 55401
612.339.5958

Acoustical Engineer
Akustiks
93 North Main Street, South
Norwalk, CT 06854
203.299.1904

MEP Engineer
JBA Consulting Engineers, Inc.
3525 N. Causeway BLVD. Suite
500 Metairie, LA 70002
504.830.0139

Civil Engineer
Linfield, Hunter, & Junius, Inc.
3606 18th Street Suite 200,
Metairie, LA 70002
504.833.5300

Architectural Historian
EHT Traceries, Inc.
1121 Fifth Street NW
Washington, DC 20001
202.393.1199

THESE DRAWINGS, SPECIFICATIONS, AND OTHER DOCUMENTS, (COLLECTIVELY, THE "DOCUMENTS") INCLUDING WITHOUT LIMITATION ELECTRONIC VERSIONS THEREOF AND THE IDEAS, DESIGNS, AND ARRANGEMENTS REPRESENTED THEREBY, ARE AND SHALL REMAIN THE PROPERTY OF MARTINEZ & JOHNSON ARCHITECTURE PC, AS DEFINED BY APPLICABLE CONTRACTUAL AGREEMENTS ("THE AGREEMENTS") AND AS PROTECTED BY THE COPYRIGHT STATUTES OF THE UNITED STATES. USE OF THE DOCUMENTS SHALL BE STRICTLY LIMITED TO THE PROJECT FOR WHICH THEY WERE PREPARED AND DEVELOPED ("THE PROJECT") PER THE TERMS OF THE AGREEMENTS. NO PART OF THE DOCUMENTS SHALL BE COPIED, DISCLOSED TO OTHERS, OR USED IN CONNECTION WITH ANY OTHER WORK OR PROJECT, OR BY ANY OTHER PERSONS FOR ANY PURPOSES, OTHER THAN THE COMPLETION OF THE PROJECT, WITHOUT THE SPECIFIC WRITTEN AUTHORIZATION OF MARTINEZ & JOHNSON ARCHITECTURE PC. THE DOWNLOADING, OPENING, OR VIEWING OF ELECTRONIC VERSIONS OF THE DOCUMENTS OR VISUAL CONTACT WITH ANY PRINTED FORM THEREOF SHALL CONSTITUTE CONCLUSIVE EVIDENCE OF ACCEPTANCE OF THESE RESTRICTIONS.

7502

DATE:	No.:	REVISION:

DATE:	ISSUE:
02.19.10	PERMIT SET
04.02.10	GMP CONTRACT SET
11.11.10	CONTRACT SET

SHEET TITLE:
WINDOW SCHEDULE

A-5.20

© 2010 M+J