

Search Results

Latitude: 30.2741

Longitude: -89.7793

**ASCE 7-10 Wind Speeds
(3-sec peak gust MPH*):**

Risk Category I: 132

Risk Category II: 142

Risk Category III-IV: 153

MRI 10 Year: 79**


MRI 25 Year: 94**

MRI 50 Year: 105**

MRI 100 Year: 115**

ASCE 7-05: 123

ASCE 7-93: 97



*MPH(Miles per hour)

**MRI Mean Recurrence Interval (years)

Users should consult with local building officials

to determine if there are community-specific wind speed requirements that govern.

WIND SPEED WEB SITE DISCLAIMER:

While the information presented on this web site is believed to be correct, ATC assumes no responsibility or liability for its accuracy. The material presented in the wind speed report should not be used or relied upon for any specific application without competent examination and verification of its accuracy, suitability and applicability by engineers or other licensed professionals. ATC does not intend that the use of this information replace the sound judgment of such competent professionals, having experience and knowledge in the field of practice, nor to substitute for the standard of care required of such professionals in interpreting and applying the results of the wind speed report provided by this web site. Users of the information from this web site assume all liability arising from such use. Use of the output of this web site does not imply approval by the governing building code bodies responsible for building code approval and interpretation for the building site(s) described by latitude/longitude location in the wind speed report.