



Rotten plywood supporting concrete walkway.

Rotten floor joist.

Rotten plywood fascia.

Rotten horizontal support.

09/27/2022