

THE PASSAGE OF FLAMES AND HOT GASES WHEN TESTED IN A
 ASTM-E814.)
 24. SERVICE COUNTER SHALL HAVE A HCP ACCESSIBLE WRITING SI
 FROM F.F. (ADAAG MANUAL 1998, PG 135)

