



Piling Inspection

March 31, 2014

For: Valerie Hulse
138 Pebble Beach Drive
Slidell, LA 70458

Alycia,

The Hulse are adding a pool to the rear of the home. The Hulse hired a pile driving company to install 8 new pilings for the pool. This pool will be supported from the new 8 pilings installed for this application.

The bulk head is not supporting the pool as the new 8 pilings are installed for this purpose.

Sincerely,

Brian Mistich, P.E.



3/31/2014

This inspection is limited to the apparent visual conditions of the structural components of this building. It does not cover, nor attempts to cover, any components, items, and/or conditions which, by their nature or location, are concealed or are difficult or hazardous to inspect, or which require the moving of furniture, flooring materials, rugs, fixtures, appliances, or any component-part nailed, bolted, or screwed down or shut. No opinions are expressed regarding conditions which could be discovered only by the disassembly of any component parts, special testing, or removal of any concealing objects.

Inspections are made under normal weather conditions, and are not opinions of the conditions of the property and/or structure which may exist under unusual weather conditions, such as, but not limited to floods, heavy rains or snows, high winds, temperature extremes, or any act of God. Specific hazardous wastes, toxic substances, toxic mold, air and water quality, communicable diseases, asbestos, soil, environmental, radon, carbon monoxide, formaldehyde, building code and termite conditions are not included in this report unless otherwise stipulated.

This report is not a warranty or guarantee of the property inspected, but it is our opinion of its condition at the time inspected. Dammon Engineering's liability shall be limited to reimbursement of the total cost of inspection.