



5-23-13

Joe France
City Of Slidell
Department of Building Safety
Slidell, La.

Ref: Southside Cafe'

Southside Cafe' has installed a Small Limited Storage Accessory building in the rear, and to make it code complainant the following shall be adhered too.

- 1) All wood strapping that is used shall be installed per the mfg recommendations which consist of all nail holes in the strapping to be used.
- 2) Bolt header of covered porch to bldg with six lag bolts to stud wall.
- 3) All blocking used for supporting the structure shall be strapped down to the asphalt using 1/2" hilti anchors at all locations. Tighten existing strapping by taking the slack out of the strap.
- 4) All lumber below BFE shall be treated with copper naphthenate (wood treatment).
- 5) Hydrostatic vents shall be installed in each wall per code.
- 6) All metal siding shall be covered or removed and a hardy board siding shall be installed.

Emmett Dammon
Dammon Engineering



DAMMON
ENGINEERING, INC.
Architects & Engineers
554 Old Spanish Trail Slidell, LA 70458 985-649-5832

Invoice

Date	Invoice #
5/22/2013	6350

Ship To	
South Side Cafe 3154 Pontchartrain Drive Slidell, LA 70458	
RE:	South Side Cafe

Description	Qty	Rate	Amount
Structural Inspection for Referenced Property		500.00	500.00
Total			\$500.00