


SECTION VIEW

Fault Distance	Feathering Distance
1/4"	5'
3/8"	7.5'
1/2"	10'

NOTES:

1. If fault is over 1/2", remove and replace the faulted area with a full depth patch.
2. All grinding to be done prior to joint sealing.
3. All work on this detail to be paid for under item: Grinding isolated joints.
4. Detail not to scale.

ROAD DESIGN	 GRINDING ISOLATED TRANSVERSE JOINTS				DESIGNED CHECKED	BCT MAC	PARISH		SHEET NO.
					DETAILED CHECKED	BCT MAC	CONTROL SECTION		
		CPR-11	NO.	DATE	REVISION DESCRIPTION	BY	DATE SHEET	03-03-11 1 OF 1	