

Down Spout
Not Connected

Rotten Piling at
Base

2024/06/24 11:09:19

Rotten Piling,
Hollow Sounding

Crack in
Foundation

2024/06/24 11:07:31

Concrete Joint

Exposed Rebar

Cracks

2024/06/24 11:05:00





No Down Spout

2024/06/24 11:06:33