

Each Disconnect uses a pitch pan/pocket. These pitch pans are not covered under siplast warranties. They are considered maintenance Items. Apparently, this is the area where the most recent roof leak occurred. Notice the sealant around each penetration.

