

INVOICE

Lower Unit Rebuilders
..
Kiln, MS 39556

lowerunitrebuilders@gmail.com
+1 (228) 326-4552

Bill to
Chuck Dammon
Chuck Dammon

Ship to
Chuck Dammon
Chuck Dammon

Invoice details

Invoice no.: 491
Terms: Due on receipt
Invoice date: 04/01/2025
Due date: 04/01/2025

#	Date	Product or service	Description	Qty	Rate	Amount
1.		Lower Unit Repair	Yamaha 25" 6CE R/H L/U for hub crack repair. Disassemble unit and weld / metal finish crack. Install seal kit, reassemble and pressure test. Fill with gearlube and install previous impeller per customer request.	1	\$720.00	\$720.00

Total	\$720.00
Payment	-\$720.00
Balance due	\$0.00

Ways to pay



Paid in Full