



St. Tammany Fire Protection District

522 Robert Boulevard
Slidell La. 70458



Phone: (985) 649-3665

Fax: 985-646-4865

This inspection is intended for your safety and the safety of the citizens of Louisiana. Your cooperation is greatly appreciated.

Occupancy: Palmetto's

Address: 1901 BAYOU LN

Date of Inspection: 1/30/2025 11:30:34 AM

Type of Inspection: Inspection - Annual

Severity	Location	Code	Reason
1 Deficient	Main and outside trailer kitchens	Hood System	Note: I did not see a sticker, indicating when the last time the hood was clean. Also, the suppression system for the cooking hood had an expired annual certification tag. Code: 96 11.4 *A certificate of vent cleaning is present 96 11.2 and 11.4 *The system is inspected at least twice a year by a certified person.
2 Note	Throughout dinning area	Assembly (Doors/Locks/Exits)	Note: dedicated or noted to have multiple forms of movement needed to open the Doors. It is recommended to remove the deadbolts and add a single movement device such as handle or push bar. With that said, this is an existing non-conforming construction in this area so to be in compliance we are requiring that at a minimum a sign is posted at each exit that reads as followed "THIS DOOR TO REMAIN UNLOCKED WHEN THE BUILDING IS OCCUPIED"

Inspection Result: Deficiencies noted

Re-Inspection Date: 3/1/2025 9:13:43 AM

Completed By:

DelBuono, Matt

Report Received By:

Brittany

R.S. 40:1621 Whoever fails to comply with any order issued by the Fire Marshal or his authorized representative under any provision of Part III, Chapter 7, of Title 40 of the Louisiana Revised Statutes of 1950, R.S. 50:1569 expected, shall be fined not more than five hundred dollars or imprisoned, for not more than six months or both. Each day's violation of an order constitutes a separate offense and may be punished at the discretion of the court.

Note: no replacements do not appear to match the configuration of the back cooking range. Owner of the building needs to contact the hood suppression company to determine the exact placement based upon the systems capabilities.

3 Deficient Side kitchen Hood System

Note: open junction box at back entrance of the kitchen, multiple refrigeration units are plugged into a single extension cord. Extension chords are plugged into other extension chords. This is not allowed. The code allows for one appliance to be plugged into an extension cord as long as the extension cord is rated to meet the appliances. Electrical needs.

4 Deficient Side yard storage area Electrical System

Code: 11.1.2.3 *No exposed wires allowed
1. 11.1.3.2 *Multiplug adaptors are not to be used a permanent wiring or receptacles
1 11.1.5.1 *Extension cord serves only 1 portable appliance
1 11.1.5.2 *Extension cord must be rate for the appliance
1 11.1.5.4 *Extension cord must be in good condition
1 11.1.5.5 *Extension cord can't be attached to a structure, or go through a building component
1 11.1.5.6 *Extension cord is not for permanent use
70 408.4(A) *Panel needs to be labeled
70 408.7 *No opening in panel
70 110.26 *Panel clearance at least 36 inch's.

5 Deficient Outside slicer/wash room Electrical System

Note: exposed wires and a nonstandard installation of a subpanel was noted. Also cover plate missing on electrical outlet by prep table. Additional exposed wire was noted at the ceiling above the entrance.

6 Deficient The Side Yard Fire Extinguishers

Note: In the side yard area we need at least two extinguishers spaced out appropriately.

Inspection Result: Deficiencies noted

Re-Inspection Date: 3/1/2025 9:13:43 AM

Completed By:

DelBuono, Matt



Report Received By:

Brittany



R.S. 40:1621 Whoever fails to comply with any order issued by the Fire Marshal or his authorized representative under any provision of Part III, Chapter 7, of Title 40 of the Louisiana Revised Statutes of 1950, **R.S. 50:1569** expected, shall be fined not more than five hundred dollars or imprisoned, for not more than six months or both. Each day's violation of an order constitutes a separate offense and may be punished at the discretion of the court.

7 Note

The Side Yard Addition Approved Plans

Note: this section of the building is a newer build that affects the means of egress as well as cooking components. A plans reviewed by the State Fire Marshalls Office is required. Contact a design professional to drop the plans of exactly what the intent of this area is to be SO the states review architect understand the entire scope.

Inspection Result: Deficiencies noted

Re-Inspection Date: 3/1/2025 9:13:43 AM

Completed By:

DelBuono, Matt



Report Received By:

Brittany



R.S. 40:1621 Whoever fails to comply with any order issued by the Fire Marshal or his authorized representative under any provision of Part III, Chapter 7, of Title 40 of the Louisiana Revised Statutes of 1950, R.S. 50:1569 expected, shall be fined not more than five hundred dollars or imprisoned, for not more than six months or both. Each day's violation of an order constitutes a separate offense and may be punished at the discretion of the court.