



## Structural Inspection

June 12, 2024

Heather M. Laughlin  
Century 21 Action Reality  
4736 West Napoleon Ave. Suite 100  
Metairie, La. 70001

Re: 73419 Allen Road  
Abita Springs, La. 70420

### Construction

One-story, wood frame, masonite siding, with a corrugated metal roof on a pier and beam foundation.

### Scope:

This inspection is limited to a visual inspection of the shell of the home, including the interior and exterior foundation of the home. No inspection of the mechanical or electrical systems was performed. This report is as outlined by the National Academy of Building Inspection Engineers and is not an explanation of cause, effect, or engineering.

### History:

Dammon Engineering was contacted to request a structural inspection of the referenced home to evaluate the structure.

### Findings:

Upon inspection of the interior of the home, it was noted that there is major structural water & termite damage to all the wood floor joist and wood beams including the roof trusses. Due to the unsafe conditions of this home, it is recommended that it be demolished.

See attachments;  
Pictures

Sincerely,  
*Brian Mistich*  
Brian Mistich, P.E.



This inspection is limited to the apparent visual conditions of the structural components of this building. It does not cover, nor attempts to cover, any components, items, and/or conditions which, by their nature or location, are concealed or are difficult or hazardous to inspect, or which require the moving of furniture, flooring materials, rugs, fixtures, appliances, or any component-part nailed, bolted, or screwed down or shut. No opinions are expressed regarding conditions which could be discovered only by the disassembly of any component parts, special testing, or removal of any concealing objects.

Inspections are made under normal weather conditions, and are not opinions of the conditions of the property and/or structure which may exist under unusual weather conditions, such as, but not limited to floods, heavy rains or snows, high winds, temperature extremes, or any act of God. Specific hazardous wastes, toxic substances, toxic mold, air and water quality, communicable diseases, asbestos, soil, environmental, radon, carbon monoxide, formaldehyde, building code and termite conditions are not included in this report unless otherwise stipulated.

This report is not a warranty or guarantee of the property inspected, but it is our opinion of its condition at the time inspected. Our liability shall be limited to reimbursement of the total cost of inspection.









