




Base line



Rear left



Front left




Rear right



Front right

Deficiencies

**Level Survey: Disclaimer**

Please note that this type of assessment is typically outside the scope of a standard home inspection and is being provided as a courtesy to our clients. This is not technically exhaustive evaluation and the home inspector is not acting in the capacity of a structural engineer. The resultant measurements of this basic elevation survey is included for informational purposes only.

Level Survey: Elevation Survey

Level survey revealed more than 6 inches of variance in the foundation. Further evaluation by a qualified structural engineer is needed.

A computerized level survey was performed and the approximate differential measurement of variance between survey points across the main area of flooring is noted.