



## Structural Inspection

April 23, 2026

Gaston B Mugnier  
505 West 5<sup>th</sup> Ave.  
Covington, La. 70433

### Construction:

Two-story, wood frame, wood veneer, wood flooring, with a composition shingle roof on a concrete foundation.

### Scope:

This inspection is limited to a visual inspection of the shell of the home, including the interior and exterior foundation of the home. No inspection of the mechanical or electrical systems was performed. This report is as outlined by the National Academy of Building Inspection Engineers and is not an explanation of cause, effect, or engineering.

### History:

Dammon Engineering was contacted to request a structural inspection of the referenced home due to hurricane damage from IDA in 2016.

### Findings:

Upon inspection, the rear of the home was damaged from a fallen tree that collapsed the roof, wall framing and floor framing.

### Conclusion:

It is my professional opinion that this home is repairable and will be in good condition once all of the repairs are completed. When work is being accomplished to rebuild the structure, fastenings and nail patterns shall meet the International Residential Code 2021 requirements for that work.

Sincerely,

*Brian Mistich*

Brian Mistich, P.E.



This inspection is limited to the apparent visual conditions of the structural components of this building. It does not cover, nor attempts to cover, any components, items, and/or conditions which, by their nature or location, are concealed or are difficult or hazardous to inspect, or which require the moving of furniture, flooring materials, rugs, fixtures, appliances, or any component-part nailed, bolted, or screwed down or shut. No opinions are expressed regarding conditions which could be discovered only by the disassembly of any component parts, special testing, or removal of any concealing objects.

Inspections are made under normal weather conditions, and are not opinions of the conditions of the property and/or structure which may exist under unusual weather conditions, such as, but not limited to floods, heavy rains or snows, high winds, temperature extremes, or any act of God. Specific hazardous wastes, toxic substances, toxic mold, air and water quality, communicable diseases, asbestos, soil, environmental, radon, carbon monoxide, formaldehyde, building code and termite conditions are not included in this report unless otherwise stipulated.

This report is not a warranty or guarantee of the property inspected, but it is our opinion of its condition at the time inspected. Our liability shall be limited to reimbursement of the total cost of inspection.