

# DAMMON ENGINEERING, INC.

dammonengineering.com

ARCHITECTS

ENGINEERS

CONSULTING

DESIGN

STUDIES

EXPERT WITNESS

1095 Florida Ave.  
Slidell, LA 70458

P.O. Box 2830  
Slidell, LA 70459

985-649-5832  
FAX 985-641-5950

LA. S.F.M. PLAN REVIEW  
 PO# 320959 REVIEWER 459  
 READING FILE DATE MO 08 YR 10  
 ORIG. TO: \_\_\_\_\_  
 SENDER  APPL. \_\_\_\_\_ OWNER \_\_\_\_\_  
 CC'S \_\_\_\_\_  
 COPYWHAT PGS. Copy to file  
 B.R. \_\_\_\_\_ N.O. \_\_\_\_\_ ALEX \_\_\_\_\_ LAF. \_\_\_\_\_  
 SHREVE \_\_\_\_\_ HO. FILE \_\_\_\_\_ HO. DEPT. \_\_\_\_\_  
 DET FILE \_\_\_\_\_ HR FILE \_\_\_\_\_ NON-REQ. SYST. \_\_\_\_\_  
 OTHER \_\_\_\_\_

July 16, 2010

Attn: Mr. David Jones  
Office of State Fire Marshall  
8181 Independence Blvd.  
Baton Rouge, LA 70806

Re: **St. Tammany Parish Slidell Administrative Complex**  
**520 Old Spanish Trail**  
**Slidell, LA 70458**  
**PO320959**

Dear Mr. Jones,

I am writing this letter to address another minor concern regarding the above referenced project.

If you will recall this is a project where the original review set was lost by the original contractor, resulting in a resubmittal/restamp with an amended letter by you dated January 13, 2009, copy attached. I have also attached a copy of your original review letter dated February 13, 2007.

It appears that the attached sheets were inadvertently omitted from that resubmittal/restamp process.

Please restamp these sheets to be included in the restamp set.

Please contact me if I can further assist you in this resubmittal/restamp

Sincerely,



Robert Wiltse  
Chief Architect  
Dammon Engineering, Inc.

INCLUDE THE ATTACHED SHEETS WITHIN THE PREVIOUS SET THAT WAS ISSUED FOR A RESTAMP



RECEIVED

8/31/10

JUL 21 2010

STATE FIRE MARSHAL  
ARCHITECTURAL SECTION