

DAMMON ENGINEERING, INC.

dammonengineering.com

CONSULTING

DESIGN

STUDIES

EXPERT WITNESS

1095 Florida Ave.
Slidell, LA 70458

P.O. Box 2830
Slidell, LA 70459

985-649-5832
FAX 985-641-5950


May 22, 2007

Lanco Construction, Inc.
5816 Plauche Ct.
Jefferson, La. 70123

Attn: Ron Blair
Ref: Addendum to strapping

All foundation corners shall be strapped in each direction using Simpson straps #PHD2-SDS3 against double studs.

Thanks
Chuck Dammon
Dammon Engineering



DAMMON ENGINEERING, INC.

dammonengineering.com

CONSULTING

DESIGN

STUDIES

EXPERT WITNESS

1095 Florida Ave.
Slidell, LA 70458

P.O. Box 2830
Slidell, LA 70459

985-649-5832
FAX 985-641-5950

August 24, 2007

City Of Biloxi Building Code Plan Review
Biloxi Building Code Office
676 Dr. Martin Luther King Blvd.
Biloxi, MS.
Attn: Michael Hornbeck

Ref: La Quinta Inn Suites
Cedar Lake Road
Biloxi, MS.

Dear Mr. Hornbeck

- 1) All firewalls shall extend tight to the underside of the deck except the third floor corridor ceiling.
- 2) Previously we had submitted a change on the corner hold down brackets. Please see the enclosed letter.
- 3) Originally we called out on the plans for I trusses, we have changed that to parallel chord trusses. And they are being installed per the manufacturing recommendations.
- 4) Hall Corridor shall be a 2x4 wood stud.
- 5) Box around penetrations through floors and fire caulk.

Please call me with any questions or concerns you may have.

Thank you,


Chuck Dammon

