

DAMMON ENGINEERING, INC.

dammonengineering.com

CONSULTING

DESIGN

STUDIES

EXPERT WITNESS

1095 Florida Ave.
Slidell, LA 70458

P.O. Box 2830
Slidell, LA 70459

985-649-5832
FAX 985-641-5950

August 24, 2007

City Of Biloxi Building Code Plan Review
Biloxi Building Code Office
676 Dr. Martin Luther King Blvd.
Biloxi, MS.
Attn: Michael Hornbeck

Ref: La Quinta Inn Suites
Cedar Lake Road
Biloxi, MS.

Dear Mr. Hornbeck

- 1) All firewalls shall extend tight to the underside of the deck except the third floor corridor ceiling.
- 2) Previously we had submitted a change on the corner hold down brackets. Please see the enclosed letter.
- 3) Originally we called out on the plans for I trusses, we have changed that to parallel chord trusses. And they are being installed per the manufacturing recommendations.
- 4) Hall Corridor shall be a 2x4 wood stud.
- 5) Box around penetrations through floors and fire caulk.

Please call me with any questions or concerns you may have.

Thank you,

Emmett Dammon