



August 18, 2016

Attn: Mr. Greg Gordon
Building Inspector
City Of Slidell
Slidell, LA

Re: Bayou Baptist Church
1341 Sullivan Drive
Slidell, La. 70460

K.B. Kaufmann has made some changes at the site.

They have opted to use the windstorm sheathing around the exterior of the bldg. therefore eliminating the Simpson Strapping in these areas from the base plate to the top plate including the strapping at the window framing.

Instead of the Simpson Strapping for the roof rafters, collar bracing was used at ever rafter at the apex. Also the hallway ceiling joist was turned due to the fire rating for these areas and make for easier installation of fire proofing.

Dammon Engineering agrees to these changes.

If you have any questions, or require additional information, please feel free to call.

Sincerely,

Chuck Dammon

Chuck Dammon
Dammon Engineering, Inc.