

# DAMMON ENGINEERING, INC.

dammonengineering.com

*CONSULTING*

*DESIGN*

*STUDIES*

*EXPERT WITNESS*

1095 Florida Ave.  
Slidell, LA 70458

P.O. Box 2830  
Slidell, LA 70459

985-649-5832  
FAX 985-641-5950

February 18, 2008

City Of Biloxi Building Code Plan Review  
Biloxi Building Code Office  
676 Dr. Martin Luther King Blvd.  
Biloxi, MS.  
Attn: Michael Hornbeck

Ref: La Quinta Inn Suites  
Cedar Lake Road  
Biloxi, MS.

Dear Mr. Hornbeck

I have instructed the contractor on how to repair the roof truss that was noted to be loose in the attic. I have inspected the repair and found it to be acceptable.

Please call me with any questions or concerns you may have.

Thank you,

Emmett Dammon