

# DAMMON ENGINEERING, INC.

dammonengineering.com

*CONSULTING*

*DESIGN*

*STUDIES*

*EXPERT WITNESS*

1095 Florida Ave.  
Slidell, LA 70458

P.O. Box 2830  
Slidell, LA 70459

985-649-5832  
FAX 985-641-5950

September 11, 2007

City Of Biloxi Building Code Plan Review  
Biloxi Building Code Office  
676 Dr. Martin Luther King Blvd.  
Biloxi, MS.  
Attn: Michael Hornbeck

Ref: La Quinta Inn Suites  
Cedar Lake Road  
Biloxi, MS.

Dear Mr. Hornbeck

3 rd floor stud walls shall be strapped to the top plate using H-8 straps. The elevator shaft was enlarged into the attic, which required the roof truss to be modified. The vent shafts for the bathrooms shall be enclosed using three layers of 5/8" type "X" from the top of the shaft. The original floor assembly was stated to be Design No. L531, now we have chosen to utilize Design No. L532 for the floor assembly.

Please call me with any questions or concerns you may have.

Thank you,

Emmett Dammon