

## UPDATING INSTRUCTIONS FOR MAY 2006

Copyright 2006 The American Institute of Architects (AIA)  
Exclusively published and distributed by Architectural Computer Services, Inc. (ARCOM) for the AIA

The CD-ROM contains complete libraries, including new, updated, and revised Sections; after installing the files, no further action is required. The CD-ROM also includes the Table of Contents, these Updating Instructions, and Revision Summary.

- |  |  |
|--|--|
| <ul style="list-style-type: none"> <li>❑ 057113 - FABRICATED METAL SPIRAL STAIRS</li> <li>❑ 064200 - WOOD PANELING</li> <li>❑ 084243 - INTENSIVE CARE UNIT/CRITICAL CARE UNIT (ICU/CCU) ENTRANCES</li> <li>❑ 092713 - GLASS-FIBER-REINFORCED PLASTER (GFRP) FABRICATIONS</li> <li>❑ 096229 - CORK FLOORING</li> <li>❑ 096466 - WOOD ATHLETIC FLOORING</li> <li>❑ 096516.13 - LINOLEUM FLOORING</li> <li>❑ 096536 - STATIC-CONTROL RESILIENT FLOORING</li> <li>❑ 097713 - STRETCHED-FABRIC WALL SYSTEMS</li> <li>❑ 097723 - FABRIC-WRAPPED PANELS</li> <li>❑ 099419 - MULTICOLOR INTERIOR FINISHING</li> <li>❑ 102113.40 - STONE TOILET COMPARTMENTS</li> <li>❑ 105116 - WOOD LOCKERS</li> <li>❑ 123200 - MANUFACTURED WOOD CASEWORK</li> <li>❑ 123553 - LABORATORY CASEWORK</li> </ul> | <ul style="list-style-type: none"> <li>Add updated Section, dated 3/06, which replaces existing SECTION 057113 - FABRICATED METAL SPIRAL STAIRS, dated 8/02.</li> <li>A revision was made to the Section.</li> <li>Add updated Section, dated 3/06, which replaces existing SECTION 084243 - INTENSIVE CARE UNIT/CRITICAL CARE UNIT (ICU/CCU) ENTRANCES, dated 11/01.</li> <li>A revision was made to the Section.</li> <li>Add updated Section, dated 3/06, which replaces existing SECTION 096229 - CORK FLOORING, dated 8/05.</li> <li>A revision was made to the Section.</li> <li>A revision was made to the Section.</li> <li>A revision was made to the Section.</li> <li>A revision was made to the Section.</li> <li>A revision was made to the Section.</li> <li>A revision was made to the Section.</li> <li>A revision was made to the Section.</li> <li>A revision was made to the Section.</li> <li>Add updated Section, dated 3/06, which replaces existing SECTION 105116 - WOOD LOCKERS, dated 8/00.</li> <li>A revision was made to the Section.</li> <li>A revision was made to the Section.</li> </ul> |
|--|--|

### UPDATE SUMMARY

Existing Sections	31
Updated Sections	4
Revised Sections	11
New Sections	0
Discontinued Sections	0
<b>Total Sections</b>	<b>31</b>