

UPDATING INSTRUCTIONS FOR MAY 2006

Copyright 2006 The American Institute of Architects (AIA)
Exclusively published and distributed by Architectural Computer Services, Inc. (ARCOM) for the AIA

The CD-ROM contains complete libraries, including new, updated, and revised Sections; after installing the files, no further action is required. The CD-ROM also includes the Table of Contents, these Updating Instructions, and Revision Summary.

- 01352 - LEED REQUIREMENTS Add updated Section, dated 5/06, which replaces existing SECTION 01352 - LEED REQUIREMENTS, dated 2/03.
- 05715 - FABRICATED SPIRAL STAIRS Add updated Section, dated 5/06, which replaces existing SECTION 05715 - FABRICATED SPIRAL STAIRS, dated 8/02.
- 06640 - PLASTIC PANELING Add updated Section, dated 5/06, which replaces existing SECTION 06640 - PLASTIC PANELING, dated 2/06.
- 08212 - STILE AND RAIL WOOD DOORS Add updated Section, dated 5/06, which replaces existing SECTION 08212 - STILE AND RAIL WOOD DOORS, dated 11/01.
- 08343 - ICU/CCU ENTRANCE DOORS Add updated Section, dated 5/06, which replaces existing SECTION 08343 - ICU/CCU ENTRANCE DOORS, dated 11/01.
- 08411 - ALUMINUM-FRAMED ENTRANCES AND STOREFRONTS Add updated Section, dated 5/06, which replaces existing SECTION 08411 - ALUMINUM-FRAMED ENTRANCES AND STOREFRONTS, dated 11/05.
- 09629 - CORK FLOORING Add updated Section, dated 5/06, which replaces existing SECTION 09629 - CORK FLOORING, dated 8/05.
- 09720 - WALL COVERINGS Add updated Section, dated 5/06, which replaces existing SECTION 09720 - WALL COVERINGS, dated 2/01.
- 10101 - VISUAL DISPLAY SURFACES Add updated Section, dated 5/06, which replaces existing SECTION 10101 - VISUAL DISPLAY SURFACES, dated 5/01.
- 10125 - DISPLAY CASES Add updated Section, dated 5/06, which replaces existing SECTION 10125 - BULLETIN BOARDS AND DISPLAY CASES, dated 5/01.
- 10505 - METAL LOCKERS Add updated Section, dated 5/06, which replaces existing SECTION 10505 - METAL LOCKERS, dated 8/01.

UPDATING INSTRUCTIONS FOR MAY 2006

□ 10506 - WOOD LOCKERS

Add updated Section, dated 5/06, which replaces existing SECTION 10506 - WOOD LOCKERS, dated 8/00.

UPDATE SUMMARY

Existing Sections	148
Updated Sections	12
Revised Sections	0
New Sections	0
Discontinued Sections	0
Total Sections	148