

Full Router & Gateway List By Make/Model

- [Introduction](#)
- [Recommended Router List](#)
- [Recommended LAN Configurations](#)
- [Recommended Switches](#)
- [Critically Important Information For All Devices](#)
- [Common Tools And Downloads](#)
- [Quick Links](#)
- [Incompatible Routers/Gateways & Other Categories](#)
- [Bandwidth Requirements](#)
- [Router/Gateway Requirements](#)

List Of All Routers & Gateways		
Manufacturer	Model	Compatibility Status
2Wire/Pace		
	2-Wire and Pace Internet Gateways: <ul style="list-style-type: none"> • Provided by AT&T and other ISPs • Models include but are not limited to: <ul style="list-style-type: none"> ◦ Pace PLC 2801HGV ◦ Pace PLC 5031NV ◦ Pace PLC 5168NV-110 ◦ And other models 	Incompatible.
Actiontec		
	CenturyLink C1000a	Serviceable (depending on model and firmware).
	CenturyLink PK5000 & PK5000a	Serviceable (depending on model and firmware).
	CenturyLink Actiontec Q2000	Serviceable.
	Frontier Actiontec F2250 Wireless VDSL Modem/Router	Serviceable.

	Actiontec MI424 Series	Serviceable.
	Verizon Actiontec 1000 Series	Incompatible.
	Verizon Actiontec 2000 Series	Incompatible.
	Verizon Actiontec GT784WN & GT784WNV	Incompatible.
	Verizon Actiontec GT704WG	Incompatible.
AdTran		
	NetVanta 3200	Serviceable.
Apple		
	Airport Extreme & Airport Time Machine: <ul style="list-style-type: none"> • 2013 to 2014 Models • Pre-2013 Models 	Not Recommended.
Arris/Motorola		
	\	
	Arris Comcast Xfinity TG852G	Incompatible.
	Arris Comcast Xfinity TG862G & TG862G-CT Gateway YN3720	Incompatible.
	Arris/Motorola Netopia 2000-series	Serviceable.
	Arris/Motorola Netopia 3000-series	Serviceable.
	Motorola/Arris NVG510	Incompatible.
	Arris/Motorola NVG589	Incompatible.
	Motorola/Arris SBXXXX (SurfBoard) Series Cable Modems	Serviceable.
	Motorola/Arris SBG6580 Cable Gateway	Incompatible.
	Time Warner Arris TG862G modem	Serviceable.
	Time Warner Arris TG1672	Serviceable.
	Arris DG860	Not Recommended.
	Arris/Motorola DG860A	Serviceable.
	Arris DG1670A modem	Serviceable.
	AT&T Arris NVG595 modem	Incompatible.
	AT&T Arris BGW210-700 modem	Incompatible.
	Arris TG1682G	Incompatible.
Asus		
	Asus RT-series Routers -- RT-AC68R, RT-AC68U, RT-AC66R, RT-AC66U, RT-N66R, RT-N66U, RT-AC56U, RT-N56R, RT-N56U, RT-N14U, RT-N16, RT-N16R, RT-N12B1, RT-N10+, & others	Serviceable.
	RT-Series routers running Asus Merlin-WRT	Serviceable.
Barracuda		
	Barracuda Firewalls	Serviceable.

Belkin		
	F5D, F6D, F7D, FDS, F9K Series, Any	Incompatible.
Buffalo		
	Buffalo DD-WRT Routers	Serviceable.
Checkpoint		
	Checkpoint UTM Firewalls	More Information Needed.
Cisco		
	ASA-series and other Cisco IOS Firewalls	Serviceable.
	Catalyst-series Managed Switches	Serviceable.
	Other Cisco Managed Switches (Layer-3, IOS)	
	Comcast Cisco DPC3939B	Serviceable if bridged.
	Comcast Cisco DPC3941B	Serviceable if bridged.
	DDR2200	Serviceable.
	DPC3825	More Information Needed.
	Meraki M6x and Z1 Cloud Management	Serviceable.
	Cox Cisco DPC3829AD	Serviceable if bridged.
	Cisco PIX506E Security appliance	Serviceable.
	RV016	Not Recommended.
	RV042: <ul style="list-style-type: none"> RV042-Hardware-Version-3-Only <i>Not the Linksys-branded RV042/RV042G</i> 	Not Recommended.
	RV082	Not Recommended.
	RV110W	Not Recommended.
	RV120W	Not Recommended.
	RV130W	Incompatible.
	RV160	Not Recommended.
	RV180	Not Recommended.
	RV180W	Not Recommended.
	RV215W	Not Recommended.
	RV220W	Not Recommended.

	RV320	Not Recommended.
	RV325	Not Recommended.
	Cisco WRVS4400N	Not Recommended.
Comtrend		
	CT-5361T and CT-5611T	Not Recommended.
DD-WRT		
	Routers running the DD-WRT firmware	Serviceable.
D-Link		
	DI-series - ***Not the DIR-series***	Incompatible.
	DIR-series and EBR-series	Incompatible.
	D-Link DIR-130	Incompatible.
Draytek		
	DrayTek Firewalls	Serviceable.
Edgewater		
	Edgewater 200AE2	Serviceable.
Frontier		
	Frontier Actiontec MI424 Series	Serviceable.
	Frontier FiOS Quantum G1100 modem	Non-Serviceable.
Fortigate		
	FortiGate / FortiNet / FortiWifi Firewalls	Serviceable.
Fry's		
	FR-300RTR	Not Recommended.
Google		
	Google Fiber Network Box	Serviceable.
Hitron		

	CGN3	Incompatible.
	CGNM 3552	Serviceable.
Juniper		
	SSG-5	Serviceable.
Linksys		
	'EA' series routers	Incompatible.
	'E' series routers	Not Recommended.
	RV42 - Not The Cisco RV042/RV042G	Not Recommended.
	RV82 - Not The Cisco RV082	Not Recommended.
	WRT120N	Incompatible.
	WRT150N	Incompatible.
	WRT160N	Serviceable, but not recommended, due to age. Can be flashed with DD-WRT.
	WRT300N	Incompatible.
	WRT310N	Not Recommended.
	WRT610N	Not Recommended.
	WRT54G-Hardware-Versions 4, 3, 2, 1.1, 1.0 running the stock Linksys firmware	Incompatible.
	WRT54G-Hardware-Versions 6, 8.0, 8.1, 8.2	Not Recommended.
	WRT54G2-series	Not Recommended.
	WRT54GS-series	Serviceable, but not recommended, due to age.
	WRT54-series routers with DD-WRT firmware	Serviceable.
	X2000	Incompatible.
Linux		
	General Instructions For Undocumented Linux Firewalls	Serviceable.
	pfSense Linux Firewalls	Serviceable.
	Shorewall Linux Firewalls	Serviceable (maybe), more Information Needed.
	Sophos Linux Firewalls	Serviceable.

Luxul		
	XBR-2300 XenSmart	Incompatible.
Motorola		
	The company Arris acquired Motorola. See the Arris section at the top of this article for Motorola devices.	
Mikrotik		
	Mikrotik Routers	Serviceable.
	Mikrotik hAP ac2	Recommended.
Netgear		
	Comcast Netgear CG3000DCR Gateway	Incompatible.
	Cox Cable Netgear CG3000D Gateway	Incompatible.
	DGND3700	Not Recommended.
	FVS-124G Firewall	Incompatible.
	FVS-314-series	Incompatible.
	FVS-318-series	Not Recommended.
	Instructions For Many Netgear Routers	Not Recommended.
	R4500	Not Recommended.
	R7000	Not Recommended.
	RP114	Incompatible.
	WGR614v9	Not Recommended.
	WNR1000v3	Not Recommended.
	WNR2000v1	Incompatible.
	WNR2000v2	Not Recommended.
	WNR2000v3	Not Recommended.
	WNR2000v4	Incompatible.
	WNR2500	Incompatible.
	WDNR3300	Incompatible.
	WNDR3400	Not Recommended.
	WNDR3700	Not Recommended.
	WNDR3800	Incompatible.
	WNDR3800CH	Incompatible.
	WNDR4300	Not Recommended.
	WNDR4500	Not Recommended.

	WPN824 & WPN824N	Incompatible.
pfSense		
	pfSense Linux Firewalls	Recommended.
Sagemcom		
	Sagemcom F@st 5260	Incompatible.
SonicWalls		
	New SonicWalls: <ul style="list-style-type: none"> • With The White/Blue User Interface • Known As SonicOS Enhanced 	Recommended.
	Old SonicWalls: <ul style="list-style-type: none"> • With The Green/Blue/Gray User Interface • Known As SonicOS Standard 	Serviceable.
Sophos		
	Sophos UTM - 9 Configuration	Serviceable.
SMC		
	Comcast Business Gateway SMCD3G & SMC8014	Recommended.
	Comcast Business Gateway SMCD3G-NV	Incompatible.
Technicolor		
	Comcast TC8305C Gateway	Incompatible.
	Cox Technicolor DPC3848VE (DOCSIS 3.0) gateway	Incompatible.
	TimeWarner Technicolor TC8715 modem	Incompatible.
Tenda		
	Tenda W268R	Incompatible.
TrendNET		
	TEW-639GR	Not Recommended.
	TEW-711BR	Incompatible.
	TEW-731-BR	Incompatible.
	TW100-S4W1CA	Incompatible.

TP-Link		
	TP-Link TL-ER6020	Not Recommended.
	TP-Link TL-WR1043ND V2	Not Recommended.
	TP-Link Touch P5	Not Recommended.
	TP-Link Archer C7 (AC1750)	Not Recommended.
Ubee		
	DDW3610	Incompatible.
	DBW3611	Incompatible.
	Instructions For Most Ubee Gateways	Incompatible.
Ubiquiti		
	Edgemax Edgerouter	Serviceable.
	Air Router HP	Serviceable.
Vizio		
	XWR100	Incompatible.
Verizon		
	Verizon FiOS Quantum G1100 modem	Non-Serviceable.
	Verizon Actiontec MI424 Series	Serviceable.
	Verizon Actiontec 1000 Series	Not Recommended.
	Verizon Actiontec 2000 Series	Incompatible.
	Verizon Actiontec GT784WN & GT784WNV	Incompatible.
	Verizon Actiontec GT704WG	Not Recommended.
Watchguard		
	XTM Fireware Series Firewalls	Recommended.
	Firebox X Edge e-Series Firewalls	Serviceable.
Westell		
	Verizon Westell 6100-Series	Incompatible.
	Westell ProLine E90-6100 - Stock Firmware	Incompatible.
	Verizon Westell 7500-Series	Incompatible.
	Verizon Westell 9100-Series	Incompatible.
Windows Server		

	Windows Server: <ul style="list-style-type: none">• Setup As A DHCP Server,• DNS Server,• And/Or Router	Serviceable.
ZyXEL		
	CenturyLink ZyXel PK5001z	Not Recommended.
	P660HWD1	Not Recommended.
	ZyWall USG-series	Serviceable.