

## UPDATING INSTRUCTIONS FOR MAY 2006

Copyright 2006 The American Institute of Architects (AIA)  
Exclusively published and distributed by Architectural Computer Services, Inc. (ARCOM) for the AIA

The CD-ROM contains complete libraries, including new, updated, and revised Sections; after installing the files, no further action is required. The CD-ROM also includes the Table of Contents, these Updating Instructions, and Revision Summary.

- 018113 - SUSTAINABLE DESIGN REQUIREMENTS  
Add updated Section, dated 3/06, which replaces existing SECTION 018113 - SUSTAINABLE DESIGN REQUIREMENTS, dated 2/03.
- 057113 - FABRICATED METAL SPIRAL STAIRS  
Add updated Section, dated 3/06, which replaces existing SECTION 057113 - FABRICATED METAL SPIRAL STAIRS, dated 8/02.
- 066400 - PLASTIC PANELING  
Add updated Section, dated 3/06, which replaces existing SECTION 066400 - PLASTIC PANELING, dated 2/06.
- 081433 - STILE AND RAIL WOOD DOORS  
Add updated Section, dated 3/06, which replaces existing SECTION 081433 - STILE AND RAIL WOOD DOORS, dated 11/01.
- 084113 - ALUMINUM-FRAMED ENTRANCES AND STOREFRONTS  
Add updated Section, dated 3/06, which replaces existing SECTION 084113 - ALUMINUM-FRAMED ENTRANCES AND STOREFRONTS, dated 11/05.
- 084243 - INTENSIVE CARE UNIT/CRITICAL CARE UNIT (ICU/CCU) ENTRANCES  
Add updated Section, dated 3/06, which replaces existing SECTION 084243 - INTENSIVE CARE UNIT/CRITICAL CARE UNIT (ICU/CCU) ENTRANCES, dated 11/01.
- 096229 - CORK FLOORING  
Add updated Section, dated 3/06, which replaces existing SECTION 096229 - CORK FLOORING, dated 8/05.
- 097200 - WALL COVERINGS  
Add updated Section, dated 3/06, which replaces existing SECTION 097200 - WALL COVERINGS, dated 2/01.
- 101100 - VISUAL DISPLAY SURFACES  
Add updated Section, dated 3/06, which replaces existing SECTION 101100 - VISUAL DISPLAY SURFACES, dated 5/01.
- 101200 - DISPLAY CASES  
Add updated Section, dated 3/06, which replaces existing SECTION 101200 - DISPLAY CASES, dated 5/01.
- 105113 - METAL LOCKERS  
Add updated Section, dated 3/06, which replaces existing SECTION 105113 - METAL LOCKERS, dated 8/01.

## UPDATING INSTRUCTIONS FOR MAY 2006

□ 105116 - WOOD LOCKERS

Add updated Section, dated 3/06, which replaces existing SECTION 105116 - WOOD LOCKERS, dated 8/00.

### UPDATE SUMMARY

Existing Sections	148
Updated Sections	12
Revised Sections	0
New Sections	0
Discontinued Sections	0
<b>Total Sections</b>	<b>148</b>