

⚠ This is a beta release of the new ATC Hazards by Location website. Please [contact us](#) with feedback.

i The ATC Hazards by Location website will not be updated to support ASCE 7-22. [Find out why.](#)

ATC Hazards by Location

Search Information

Address: 3501 Champion Lake Blvd, Shreveport, LA 71105, USA
Coordinates: 32.4736699, -93.69144519999999
Elevation: 164 ft
Timestamp: 2024-02-05T21:16:35.018Z
Hazard Type: Wind



ASCE 7-16		ASCE 7-10		ASCE 7-05	
MRI 10-Year	72 mph	MRI 10-Year	76 mph	ASCE 7-05 Wind Speed	90 mph
MRI 25-Year	78 mph	MRI 25-Year	84 mph		
MRI 50-Year	84 mph	MRI 50-Year	90 mph		
MRI 100-Year	89 mph	MRI 100-Year	96 mph		
Risk Category I	97 mph	Risk Category I	105 mph		
Risk Category II	104 mph	Risk Category II	115 mph		
Risk Category III	110 mph	Risk Category III-IV	120 mph		
Risk Category IV	115 mph				

The results indicated here DO NOT reflect any state or local amendments to the values or any delineation lines made during the building code adoption process. Users should confirm any output obtained from this tool with the local Authority Having Jurisdiction before proceeding with design.

Please note that the ATC Hazards by Location website will not be updated to support ASCE 7-22. [Find out why.](#)

Disclaimer

Hazard loads are interpolated from data provided in ASCE 7 and rounded up to the nearest whole integer. Per ASCE 7, islands and coastal areas outside the last contour should use the last wind speed contour of the coastal area – in some cases, this website will extrapolate past the last wind speed contour and therefore, provide a wind speed that is slightly higher. NOTE: For queries near wind-borne debris region boundaries, the resulting determination is sensitive to rounding which may affect whether or not it is considered to be within a wind-borne debris region.

Mountainous terrain, gorges, ocean promontories, and special wind regions shall be examined for unusual wind conditions.

While the information presented on this website is believed to be correct, ATC and its sponsors and contributors assume no responsibility or liability for its accuracy. The material presented in the report should not be used or relied upon for any specific application without competent examination and verification of its accuracy, suitability and applicability by engineers or other licensed professionals. ATC does not intend that the use of this information replace the sound judgment of such competent professionals, having experience and knowledge in the field of practice, nor to substitute for the standard of care required of such professionals in interpreting and applying the results of the report provided by this website. Users of the information from this website assume all liability arising from such use. Use of the output of this website does not imply approval by the governing building code bodies responsible for building code approval and interpretation for the building site described by latitude/longitude location in the report.