

**Port of New Orleans
3855 France Rd.**

Meco Bldg 2



3/25/06

Attachment 1

PHOTOGRAPH DESCRIPTIONS

1. Overview of roof (area A).



2. Underside of deck.



3. Damage to roof from flying debris.



4. Damage to roof from flying debris.



5. Damage to roof.



6. Damage to roof from flying debris. Note the profile of this panel is no longer available.



7. Overview of roof (area B).



8. Overview of roof (area C).



9. Damage to roof.



10. Damage to gutter.



11. Damage to rake trim.



LAST PAGE