

existing exposed structure


new gyp. bd.  
by contractor

existing exterior wall



typical interior  
hoistway wall,  
some existing,  
some being  
replaced due  
to damage

existing concrete floor slab





existing structure

new gyp.  
bd. by  
contractor