



# Office of State Fire Marshal

8181 Independence Blvd. Baton Rouge, LA 70806  
(225) 925-4911 (800) 256-5452 Fax (225) 925-4241



## CERTIFICATE OF COMPLETION

Date: 5/3/2023

Please list all projects pertaining to the currently scheduled reviews of the building. System type refers to Architectural, Fire Alarm, Kitchen Hood/Wet Chemical Suppression, Fire Suppression, or Storage Tank.

SFM Project Number	Project Type	Contractor Signature
AR-22-009157	Final	

To arrange for inspection of the project, please contact the district office two (2) to three (3) weeks in advance. To verify inspection district and phone number please refer to the "cc" list on the last page of the State Fire Marshal review letter. The plans stamped reviewed by this office must be available on job site at time of inspection. This Certificate Of Completion must be provided to the inspecting deputy at final inspection.

This is to certify the below project

<b>Project Title From Application</b> Dr. Hontas MOB Addition		
<b>Project Address</b> 71211 LA HWY 21		
<b>City</b> COVINGTON	<b>State</b> LA	<b>Zip Code</b> 70433

was periodically observed by me, by my consultants, and/or by others in my employ during construction and, to the best of my knowledge, information and belief, has been completed in accordance with the safety provisions which were shown in the plans and specifications previously reviewed by the Fire Marshal.

**UNDER PENALTY OF LAW FOR FALSE STATEMENTS, I** (NAME OF ARCHITECT/ENGINEER IF REQUIRED, OTHERWISE OWNER)

Print Name: David Dammon

Signature: \_\_\_\_\_

Architect/ Civil Engineer License Number: \_\_\_\_\_

**CERTIFY ALL STATEMENTS CONTAINED HEREIN ARE, TO THE BEST OF MY KNOWLEDGE, INFORMATION AND BELIEF, TRUE AND CORRECT.**

### LAC 55:V:307 OBSERVATION OF CONSTRUCTION

A. For a structure which by law may only be constructed with plans prepared and certified by a licensed architect or civil engineer, it shall be the duty of the owner of such a structure to provide for periodic observation of the construction of the structure to determine if the work is proceeding in accordance with the plans and specifications as approved by the fire marshal. The observations shall be performed by a registered architect or a registered civil engineer.

B. Upon completion of such work, where the law requires the owner to engage an architect or registered civil engineer, the owner shall furnish to the fire marshal a certificate signed by a registered architect or registered civil engineer stating that the periodic observations have been made and that to the best of the architect's or engineer's knowledge, information and belief, the work was completed in accordance with those fire safety standards and regulations stipulated in the plans and specifications previously approved by the fire marshal. When the owner has not engaged an architect or registered civil engineer, and the same is not required by law, the owner must submit the certificate of completion when appropriate, but always under his signature.

C. Occupancy of a structure, watercraft or movable prior to furnishing a certificate to the fire marshal as required under this regulation is expressly forbidden by the fire marshal, unless and until a satisfactory inspection has been made by the fire marshal or his certified representative.

D. In order to comply with the requirements of §307.B, the owner must submit to the fire marshal the following certificate completed by the architect, civil engineer, or, if neither is required by law, the owner.