



Termite damaged beam supporting roof

Termite damaged beam supporting roof

Termite damaged rear porch

Termite damaged beam supporting front porch

Termite damaged front porch

Termite damaged wall supporting stairwell

Termite damage beam supporting stair landing