




Water leaking from above

A photograph showing a concrete slab with a crack and a pile cap. A red box with the text "Cracked slab" has an arrow pointing to a crack in the concrete. Another red box with the text "Space between piling and slab" has an arrow pointing to the gap between a pile and the concrete slab. The scene is outdoors with shadows cast across the concrete.

Cracked slab

Space between  
piling and slab



Rotten wood with  
twisted 6x6 suport

Loose railing

exposed decking

