



ENTRANCES

FRONT OF HOME ABOVE
WINDOW CRACK IN MORTAR
HORIZONTAL.

VERTICAL CRACK ON
LEFT SIDE OF HOME VERTICAL

REAR PORCH SMALL HAIRLINE
CRACK UNDER WINDOW
IN WALL & FLOOR OF
PORCH

CRACK ABOVE WINDOW
Bed Room

PREVIOUS REPAIR ON 2ND FLOOR
RIGHT SIDE OF HOME.

CRACK IN DINING ROOM WALL

9 MONTHS VACANT.

CRACK IN CERAMIC FLOOR
WINDOW FRONT TO REAR
& REAR ISLAND: