

Sheet rock
separated at front
door

Front door is
racked

