

A photograph of a white ceiling. At the top center, there is a rectangular air vent with horizontal slats. To the right, there is a circular recessed light fixture. A red-bordered text box is overlaid on the image, containing the text "Sheet rock separated in bathroom". A red arrow points from the text box to a crack in the white sheet rock along a joint. The walls are painted a light blue color.

Sheet rock  
separated in  
bathroom