

A photograph of a white horizontal siding exterior wall. A window with blue shutters and a green awning is visible in the upper right. A red arrow points to a gap between the siding and the structure below. A white electrical box is on the left. The house is on a wooden pier with pipes visible underneath.

siding separted in  
front of home