

A photograph showing the underside of a porch with white horizontal siding. A red arrow points to a dark, damaged structural beam. The text 'Front porch structural beam termite infested.' is written in red inside a white box. The date '09/27/2022' is printed in orange in the bottom right corner. The background shows green trees and a house in the distance.

Front porch  
structural beam  
termite infested.

09/27/2022