

A photograph showing a concrete slab with a crack and a pile cap. A red box on the left contains the text "Cracked slab" with a red arrow pointing to a crack in the concrete. Another red box on the right contains the text "Space between piling and slab" with a red arrow pointing to the gap between a pile and the concrete. The scene is outdoors with shadows cast across the concrete.

Cracked slab

Space between
piling and slab