

S.W. COLUMN
WEST SIDE OF COLUMN
CRACK IS APPROX 14" HIGH



907 S. HARRISON
COVINGTON, LA

#1

SOUTHWEST CORNER OF COLUMN
NOTE THAT BRICK FACADE IS TO EDGE
OF SLAB ON SOUTH SIDE



907 S. HARRISON
COVINGTON, LA
#2

S.W. COLUMN



#3

907 S. HARRISON
COVINGTON, LA

S.W. COLUMN
HAIRLINE CRACKS IN FACED



907 S. HARRISON
COVINGTON LA

#5-

S.W. CORNER
CLOSE UP OF #3



#4

907 S. HARRISON
COWINGTON VA