



1  
C-1

**SURVEY**  
SCALE 1/8" = 1'-0"

**LEGEND**  
 [Symbol] = LIGHT STANDARD  
 [Symbol] = GRAVITY POLE  
 [Symbol] = FIRE HYDRANT  
 [Symbol] = UTILITY CULVERT LINE

401 EXISTING PARKING SPACES

**NEW CANOPY**

**PONTCHARTRAIN DRIVE**  
(U.S. HWY. 11)

Survey of  
**LOT 3-A TAMMANY MALL SUBDIVISION**  
**SECTION 44 - TOWNSHIP 9 SOUTH, RANGE 14 EAST**  
**CITY OF SLIBELL**  
**ST. TAMMANY PARISH, LOUISIANA**

Note: This is to certify that I have consulted the Federal Insurance Administration Flood Hazard Boundary Maps and the property boundaries shown hereon are located in a special flood hazard area. It is located in Flood Zone AE. (FEMA 100-1-1-95)  
 FROM: [Name] 2/22/2014 10:15:02 Rev: 2-21-95

REFERENCE MAP:  
 MAP OF REVISIONS OF A PORTION OF LOT "C" TAMMANY MALL SUBDIVISION, LOTS 3-A AND 3-B, BY GEORGE H. POPE, L. DATED OCT. 6, 1998. FILED FOR RECORD MAR. 10, 2000. MAP FILE NO. 1811.

Donald W. Brown, P.E.  
 Professional Land Surveyor  
 LA Registration No. 04386

**NOTES REGARDING SERVICES AND RESTRICTIONS:**  
 1. THIS MAP WAS PREPARED BY THE SURVEYOR FROM THE FIELD AND THE SURVEYOR HAS CONDUCTED A VISUAL INSPECTION OF THE PROPERTY AND HAS FOUND THE PROPERTY TO BE ACCURATELY LOCATED IN A SPECIAL FLOOD HAZARD AREA.  
 2. THE SURVEYOR HAS CONDUCTED A VISUAL INSPECTION OF THE PROPERTY AND HAS FOUND THE PROPERTY TO BE ACCURATELY LOCATED IN A SPECIAL FLOOD HAZARD AREA.  
 3. THE SURVEYOR HAS CONDUCTED A VISUAL INSPECTION OF THE PROPERTY AND HAS FOUND THE PROPERTY TO BE ACCURATELY LOCATED IN A SPECIAL FLOOD HAZARD AREA.  
 4. THE SURVEYOR HAS CONDUCTED A VISUAL INSPECTION OF THE PROPERTY AND HAS FOUND THE PROPERTY TO BE ACCURATELY LOCATED IN A SPECIAL FLOOD HAZARD AREA.  
 5. THE SURVEYOR HAS CONDUCTED A VISUAL INSPECTION OF THE PROPERTY AND HAS FOUND THE PROPERTY TO BE ACCURATELY LOCATED IN A SPECIAL FLOOD HAZARD AREA.  
 6. THE SURVEYOR HAS CONDUCTED A VISUAL INSPECTION OF THE PROPERTY AND HAS FOUND THE PROPERTY TO BE ACCURATELY LOCATED IN A SPECIAL FLOOD HAZARD AREA.  
 7. THE SURVEYOR HAS CONDUCTED A VISUAL INSPECTION OF THE PROPERTY AND HAS FOUND THE PROPERTY TO BE ACCURATELY LOCATED IN A SPECIAL FLOOD HAZARD AREA.  
 8. THE SURVEYOR HAS CONDUCTED A VISUAL INSPECTION OF THE PROPERTY AND HAS FOUND THE PROPERTY TO BE ACCURATELY LOCATED IN A SPECIAL FLOOD HAZARD AREA.  
 9. THE SURVEYOR HAS CONDUCTED A VISUAL INSPECTION OF THE PROPERTY AND HAS FOUND THE PROPERTY TO BE ACCURATELY LOCATED IN A SPECIAL FLOOD HAZARD AREA.  
 10. THE SURVEYOR HAS CONDUCTED A VISUAL INSPECTION OF THE PROPERTY AND HAS FOUND THE PROPERTY TO BE ACCURATELY LOCATED IN A SPECIAL FLOOD HAZARD AREA.

REVISED SITE PARKING TO NEW BRANCH LIBRARY, RE-A1

LOT 1-A

LOT 2-A

SUBJECT